

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
K-2942

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - A" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- SWD Well	7. Unit Agreement Name
2. Name of Operator BTA OIL PRODUCERS	8. Farm or Lease Name Pray #1, SWD
3. Address of Operator 104 South Pecos Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER F, 1980 FEET FROM THE North LINE AND 1980 FEET FROM THE West LINE, SECTION 5 TOWNSHIP 10-S RANGE 36-E NMPM.	10. Field and Pool, or Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 4058'	12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 12,500' PROCEDURE

1. Establish injection rate using formation water.
2. Pull 5-1/2" csg. 515' ±
3. Run 2-3/8" tbg to 5-1/2" csg stub - 515'±
4. Pump 325 sx Class "H" cmt as follows:
200 sx w/1/2#/sx Flo Seal
35 Bbls. salt gel
50 sx w/1/4#/sx Flo Seal
150 Bbls. salt gel
75 sx w/1/4#/sx Flo Seal
5. Set 50 sx Plug @470'
6. Set 25 sx Plug @ Surface.
7. Install Dry Hole Marker per NMOCC Regulations.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Bob K. Newland BOB K. NEWLAND TITLE Regulatory Supervisor DATE 8/8/77

APPROVED BY John W. Runyan TITLE Geologist DATE AUG 11 1977

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

DEC 1 1977

OIL CONSERVATION COMM.
HOBBS, N. M.