

PETROLEUM PRODUCTION MANAGEMENT, INC.

P.O. BOX 957

CROSSROADS, NEW MEXICO 88114

(505) 675-2478

December 7, 1990

N.M. Oil Conservation Commission P.O. Box 1980 Hobbs, New Mexico 88240

Attn: Jerry Sexton

Re: Max Pray No. 2 SWD Pressure Test Annulus

Dear Mr. Sexton:

On December 3, 1990, we rigged up Meenar Well Service on the captioned well. We got out of the hole with all the tubing and the packer on December 4, 1990. Upon visually inspecting the tubing and packer, we discovered a hole in the packer. On December 5, 1990, we were shut down waiting on a replacement packer.

On December 6, 1990, we went in the hole with a replacement Guiberson Uni-packer VI and ran 360 joints of 2 7/8" Duoline tubing. After pumping packer fluid down the annulus, we set the packer and pressure tested it to 340#.

Enclosed, please find the test chart. We ran the test for 30 minutes at 340#.

Gary(JT. Cothran District Superintendent

GTC/ts