

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SAN JOSE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-2943

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input type="checkbox"/> WELL GAS <input checked="" type="checkbox"/> WELL OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator W. K. Byrom	8. Farm or Lease Name T. P. State
3. Address of Operator Box 147 - Hobbs, N. M. 88240	9. Well No. 1
4. Location of Well UNIT LETTER <u>K</u> . <u>1980</u> FEET FROM THE <u>West</u> LINE AND <u>1980</u> FEET FROM THE <u>South</u> LINE, SECTION <u>10</u> TOWNSHIP <u>10S</u> RANGE <u>36E</u> NMPM.	10. Field and Pool, or Wildcat Crossroads SA South Gas
15. Elevation (Show whether DF, RT, GR, etc.) 4024 DF	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☒  
CHANGE PLANS ☐  
OTHER ☐

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER ☐

ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-21-75: I intend to spot a 30 sack plug over the perforations at 4904 to 4932, then fill the casing with fresh 1% KCL water to protect the pipe. We will make known attempts to recover the casing in this well. I will place a 55 sack plug at 200' to cover the top of the salt section + a 10 sack plug at surface and dry hole marker. The location will be cleaned and all surface equipment removed.

And (1) 100' plug at base of salt, if not behind pipe  
(2) 100' plug at stub  
(3) 100' plug at shoe of surface cgs.  
(4) mud between all plugs.  
24 hr notice to o.c.c. before setting bottom plug.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature]  
APPROVED BY [Signature]  
CONDITIONS OF APPROVAL, IF ANY:

TITLE Geologist  
Geologist

DATE 7-21-75  
JUL 21 1975