

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

SEP 17 20 11 '69

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>Dry Hole</b>		7. Unit Agreement Name
2. Name of Operator <b>J.M. Huber Corporation</b>		8. Farm or Lease Name <b>Santa Fe "22"</b>
3. Address of Operator <b>1900 Wilco Building, Midland, Texas 79701</b>		9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>B</b> , <b>330</b> FEET FROM THE <b>North</b> LINE AND <b>2310</b> FEET FROM THE <b>East</b> LINE, SECTION <b>22</b> TOWNSHIP <b>10-S</b> RANGE <b>36-E</b> NMPM.		10. Field and Pool, or Wildcat <b>S. Crossroads Strawn</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4009' GR</b>		12. County <b>Lea</b>

### Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Shot off and pulled 3528' 5-1/2" casing.  
Shot off and pulled 1040' 8-5/8" casing.  
Set cement plugs as follows:

25 sx 3578' - 3478'  
25 sx 1090' - 990'  
25 sx 360' - 300'  
10 sx in top

Installed marker. Plugged and abandoned 9/5/69.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Raymond* TITLE District Production Supt. DATE 9/5/1969

APPROVED BY *Nathan E. Clegg* TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: