

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPlicate
(Other instructions
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NY 01744

6. INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT TO DRILL" for such proposals.)

1. ☐ OIL WELL ☒ GAS WELL ☐ OTHER	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Rodman Petroleum Corporation	8. NAME OF LEASE NAME Federal Bremond
3. ADDRESS OF OPERATOR Box 3826, Odessa, Texas	9. WELL NO.
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface Unit D, 660' FNL & 660' FNL	10. FIELD AND ZONE, OR WITHOUT Allison, Penn
14. PERMIT NO.	11. SEC., T., R., OR BLM. AND SOLVY OR AREA Sec. 4, T-9-S, R-37-E
15. ELEVATION (Show whether DF, W, CR, etc.) 4025' GR	12. COUNTY OR PARISH 13. STATE Lea N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PUMP OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☒	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	(Other) ☐

(Other) ☐ (Other) ☐
(Note: Report results of multiple completion on W-1.
Completion of recompleting reports and log forms.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent data, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

CASING PROGRAM: 10-3/4" csg. set @ 415' w/ 350 sks, cement circulated.
7-5/8" csg. set @ 4287' w/ 300 sks, top cement at 3250'.
4-1/2" csg. set at 9647' w/ 300 sks, top cement at 7200'.
PERFORATIONS: Open hole from 9647 to 9691', perfs. from 9625 to 9664'.
PROPOSAL: (a) Spot 100' plug or 15 sks min. plug across open hole and perforated interval.
(b) Cut and recover 4-1/2" casing at 7000'.
(c) Spot 100' plug across stub of 4-1/2" csg and across Glorietta from approx. 5500-5600'.
(d) 100' plug at 4287-4337' (7-5/8" csg. shoe).
(e) Cut and recover 7-5/8" csg. at approximately 3000'.
(f) Spot 100' plug across stub of 7-5/8" csg on anhydrite at top of salt, whichever is higher.
(g) 100' plug 365-465' (10-3/4" csg. shoe), and spot 20 sks plug at top of 10-3/4" csg. fill cellar and place marker.
(h) Mud will be used between all plugs.
(i) All offset operators have been notified.

18. I hereby certify that the foregoing is true and correct

SIGNED

J. L. OschlerTITLE Geological EngineerDate August 25, 1965

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

DATE

*See Instructions on Reverse Side

J. L. Oschler
ACTING DISTRICT ENGINEER