

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions
reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 01744

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal Brennand

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Allison Penn

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 4, T-9-S, R-37-E

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐ 11 10 31 '66
2. NAME OF OPERATOR
Rodman Petroleum Corporation
3. ADDRESS OF OPERATOR
P. O. Box 3826, Odessa, Texas
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
Unit B, 660' FNL & 1980' FEL
14. PERMIT NO.
15. ELEVATIONS (Show whether DF, RT, GR, etc.)
4022' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Started plugging operations 11-15-65

Hole circulated w/ mud

Spotted 20 sacks cmt plug from 9650-9382', above and below all perforations

Shot off 4-1/2" csg at 5822' and recovered

Spotted 20 sx cmt plug from 5872 to 5657 in and out of 4-1/2" casing stub

Spotted 25 sx cmt plug from 5602 to 5487' across Glorietta zone

Spotted 25 sx cmt plug from 4339 to 4227' at shoe of 7-5/8" casing

Shot off 7-5/8" csg at 1208' and recovered

Spotted 37 sacks cmt plug from 1260-1153 in and out of 7-5/8" stub

Spotted 50 sacks cmt plug from 455 to 348 at shoe of 10-3/4" casing

Spotted 20 sacks cmt plug in top of 10-3/4" casing

Welded 10-3/4"x1/4" plate in top of 10-3/4" casing

Placed welded marker on well and filled cellar

Cleaned and leveled location

Job complete 12-1-65

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Engineer

DATE Dec. 18, 1965

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.