

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

AUG 4 12 01 PM '65

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</p>		<p>5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/></p>
<p>1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-</p>		<p>5. State Oil & Gas Lease No.</p>
<p>2. Name of Operator GREAT WESTERN DRILLING COMPANY</p>		<p>7. Unit Agreement Name</p>
<p>3. Address of Operator P. O. Box 1659, Midland, Texas</p>		<p>8. Farm or Lease Name ODC "B"</p>
<p>4. Location of Well AND DEPTH J 1980 FEET FROM THE South LINE AND 1980 FEET FROM THE East LINE, SECTION 6 TOWNSHIP 9-S RANGE 37-E NMPM.</p>		<p>9. Well No. 1</p>
<p>10. Field and Pool, or Wildcat Allison - Penn</p>		<p>11. Field and Pool, or Wildcat Allison - Penn</p>
<p>15. Elevation (Show whether DF, RT, GR, etc.) 4032 GR</p>		<p>12. County Lea</p>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The 4-1/2" was loaded with mud. 25 sacks of cement were spotted @ 9670'. The 4-1/2" was cut and pulled @ 6039'. Set 25 sack plug @ 6039', 25 @ 5500'. 25 @ 4296'. 170' of 7-5/8 casing were cut & pulled. A 25 sack plug was set @ 970' and 10 sacks @ the surface. The well was P. & A. July 29, 1965

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED O. H. Crews TITLE Administrative Coordinator DATE August 3, 1965

APPROVED BY [Signature] TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: