NO. OF COPIES RECEIVED			Form C-103
DISTRIBUTION			Supersedes Old C-102 and C-103
SANTA FE	NEW MEXI	CO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE	]		
U.S.G.S.			5a. Indicate Type of Lease
LAND OFFICE	7		State Fee.
OPERATOR	· <del>-</del>		5. State Oil & Gas Lease No.
	ـــ		
CLINID	DV NOTICES AND D	EDORTS ON WELLS	minimizini.
(DO NOT USE THIS FORM FOR PR	OPOSALS TO DRILL OR TO D	EPORTS ON WELLS EEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. 1 C-101) FOR SUCH PROPOSALS.)	
1.	TION FOR PERMIT - (FORM	COTOTY FOR SUCH PROPOSALS.)	7. Unit Agreement Name
OIL GAS WELL WELL	OTHER-		
2. Name of a per thor			8. Farm or Lease Name
Creat Western Brilling Company			ODC "B"
Great Western Drilling Company 3. Address of Cherator			9, Well No.
D 0 Dem 1650	Wellerd Masses		2
P. O. Box 1659 4. Location of Well	midiand, lexas		10. Field and Pool, or Wildcat
	000	11aah 460	· ·
UNIT LETTER N	980 FEET FROM TH	ie West Line and 660 FEET FR	Allison-Pennsylvanian
		0 ·	
THE South LINE, SECT	10N TOW!	NSHIP 9-5 RANGE 37-E NM	PM. ((((((()()()()()()()()()()()()()()()()
mmmmm	15 57	(Show whether DF, RT, GR, etc.)	12, County
	15. Elevation		
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	.111117	4030 GR	Lea
Check	Appropriate Box To	o Indicate Nature of Notice, Report or (	Other Data
NOTICE OF I	NTENTION TO:	SUBSEQUE	NT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AN	D ABANDON X REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE	PLANS CASING TEST AND CEMENT JOB	
		OTHER	
OTHER			
			7.00
work) SEE RULE 1103.	perations (Clearly state a	all pertinent details, and give pertinent dates, includ	ing estimated date of starting any proposed
The hole w	ill be loaded w	ith 10 # mud. The pay zone 964	6 - 76 will be covered
with a 25 sack	plug to 9500'.	Some 6000' of 4 1/2" will be p	ulled and 25 sacks
	<b>F</b>	•	
placed in this	stub. 25 sacks	@ 5500', 25 sacks in the shoe	of the 7 5/8" @ 4280'.
<b>P10000 III</b> IIII		• • • • • • • • • • • • • • • • • • • •	
Some 600 of 7	5/8 will be pul	led and a 25 sack plug set in the	his stub. 25 sacks
3023 333 32 .	•,• <u></u>		
will be placed	@ 269' (shoe of	10 3/4) with 10 sacks at the s	urface.
30 p	<b>(</b>		
A cleanup	and marker will	be made.	
			· · · · · · · · · · · · · · · · · · ·
18. I hereby certify that the information	above is true and comple	ete to the best of my knowledge and belief.	
<i>6</i> ?			
SIGNED ALLE	O. H. Crews	TITLE Administrative Coordinat	or DATE June 2, 1965
<i>S</i>			
APPROVED BY		TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY			