Form	9-831	8
(Feb.	. 1951)	



(SUBMIT IN TRIPLICATE)

Budget Bureau No. 42-R358.4. Approval expires 12-31-60. Land Office Seate Fe Lease No. 1991 01.744

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

SUNDRY NOTICES	5 AND	REPORTS	ON	WELLS
----------------	-------	---------	----	-------

 SUBSEQUENT REPORT OF WATER SHUT-OFF	X
 SUBSEQUENT REPORT OF ALTERING CASING	
 SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
 SUBSEQUENT REPORT OF ABANDONMENT	
 SUPPLEMENTARY WELL HISTORY	
JRE OF REPORT, NOTICE, OR OTHER DATA)	
	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING

		<b></b>	May 8,	, 19 🍋
<b>Federal "Mi"</b> Well No <b>2</b> is located	l <b>1989</b> ft.	from [N] line and	<b>1.1980</b> ft. from $\left\{\begin{matrix} \mathbf{W} \\ \mathbf{W} \end{matrix}\right\}$ line of s	ec
ss/A of Wi/A Sec. B	9-5	37-4	NICON.	
<b>52/4 of 101/4 Boc.</b> (½ Sec. and Sec. No.)	(Twp.)	(Range)	(Meridian)	
Lest Allien (Paun) (Field)	(C	ounty or Subdivision)	Ser Heatlee (State or Territory)	

The elevation of the derrick floor above sea level is \_\_\_\_\_\_.

---

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On May 3, 1961, 4272' of 7-5/6" 26.44 new casing was comented @ 4290' with 1500 macks of Trimity Lite-Mate plus 200 macks of regular coment. Approximately 125 macks were eirculated at the surface. After 24 hours, a pressure of 1000 pai was applied at the surface. After 30 minutes there was no pressure loss. Drilling was resumed May 4, 1961.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company _	Great Mestern Drilling Company		
Address	Box 1659, Midland, Texas		
		By Officers Title Administrative Coor	