



OCT 9 1962 (SUBMIT IN TRIPLICATE)

E. W. STANDLEY
DISTRICT SUPERVISOR
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Inspected 4-6-62
O.K. for Abandonment JdB

SUNDRY NOTICES AND REPORTS ON WELLS

Budget Bureau No. 42-R358.4.
Form Approved.

Land Office New Mexico

Lease No. 0677060

Unit

RECEIVED

SEP 12 1962

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 10, 1962

Well No. 1 is located 1980 ft. from [N] line and 1980 ft. from [EX] line of sec. 20

SE/4 NW/4 20 T-9S R-37E

wildcat Lea New Mexico

The elevation of the ~~terrace floor~~ ^{ground} above sea level is 3998 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

FD 12, 190' 13 3/8" 417' 3 3/8" 64177 mud

Spot 65 sacks cement 9815-10015
Spot 35 sacks cement 7700-7800
Spot 65 sacks cement 4850-5050
Spot 35 sacks cement 4100-4200
Shoot 8-5/8" casing @ 895 and pull 895' casing.
Spot 40 sacks cement 795-895
Spot 60 sacks cement 425-325
15 sacks cement as surface plug.
Set 4" pipe marker with location and name thereon.
Location and pits have been leveled and are ready for inspection.

NOTED
OCT 10 1962
HUBBLE

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Huber Corporation, Brown and George

Address J. M. Huber Corporation

610 Midland National Bank Bldg.

Midland, Texas

By *Robert H. Smith*

Title District Superintendent