NO. OF COFIES RECEIVED		Form C-103
DISTRIBUTION	· ·	Supersedes Old C•102 and C•103
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSIO	
FILE		
U.S.G.S.	<del>-</del>	5a. Indicate Type of Lease
LAND OFFICE	<del> </del>	State X Fee
OPERATOR	<u>i                                     </u>	5. State Oil & Gas Lease No.
		E-1516
(CO NOT USE THIS FORM FO	INDRY NOTICES AND REPORTS ON WELLS OR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERV LICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
OIL GAS WELL	OTHER-	7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
TEXACO Inc.		New Mexico "AR" Sta
3. Address of Operator	0004	9. Well No.
	Hobbs, New Mexico 88240	2
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER $oldsymbol{L}$ ,	990 FEET FROM THE West LINE AND 1650	Echols (Devonian)
THE South LINE.	SECTION 2 TOWNSHIP 11-S RANGE 37-E	NMPM.
mmmm	15 Flouration (Chan unhauber DE DT CD	
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	3953' DF	Lea
	eck Appropriate Box To Indicate Nature of Notice, Re OF INTENTION TO: SU	port or Other Data  BSEQUENT REPORT OF:
<u> </u>	(P)	
PERFORM REMEDIAL WORK	PLUG AND ABANDON X REMEDIAL WORK	ALTERING CASING
TEMPORAR LY ABANDON	COMMENCE DRILLING OPNS	F=
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT	1db [
	OTHER	
OTHER		
2. Squeeze Load hole  3. Cut $5\frac{1}{2}$ " of  4. Spot $100^{\circ}$ 5. Spot $15^{\circ}$ 6. Install	perforations 11,430-11,450' w/100 sie w/ mud.  casing & pull.  (45sx.) cement plug across $5\frac{1}{2}$ " casing & plug @ surface.  dry hole marker & clean location.	
18. I hereby certify that the inform	partion above is true and complete to the best of my knowledge and belief	
APPROVED BY	One. Simul by [60 D Ramey	DATE
CONDITIONS OF APPROVAL, IF	L-St. 1, 8 19V.	