

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-73

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

1. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
2. State Oil & Gas Lease No. L-5283

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER- D&A - Re-entry
Name of Operator Yates Petroleum Corporation		
Address of Operator 207 South 4th St., Artesia, NM 88210		
Location of Well UNIT LETTER A 660 FEET FROM THE North LINE AND 658 FEET FROM THE East LINE, SECTION 12 TOWNSHIP 11S RANGE 37E NMPM.		

3. Unit Agreement Name
4. Farm or Lease Name Shell "PD" State
5. Well No. 1
6. Field and Pool, or Wildcat Undesignated

7. Elevation (Show whether DF, RT, GR, etc.) 3934' GR	8. County Lea
--	------------------

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
REPAIR OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged and abandoned well as follows:

- Plug #1 - 10700' set CIBP w/35' Class "C" above Strawn perfs
- Plug #2 - 9650' set CIBP w/35' Class "C" above Penn perfs
- Plug #3 - 7770-7544' w/25 sacks Class "C" above Abo perfs
- Plug #4 - 5780-5454' w/25 sacks Class "C" above Yeso perfs
- Plug #5 - 5026-4926' w/35 sacks Class "C" above 5-1/2" casing stub
- Plug #6 - 4440-4318' w/35 sacks Class "C" above 8-5/8" casing shoe
- Plug #7 - 2050-1945' w/30 sacks Class "C" above Salt top
- Plug #8 - 410-305' w/30 sacks Class "C" above 13-3/8" casing shoe
- Plug #9 - Surface w/10 sacks Class "C"

Heavy mud placed between all plugs. Installed regulation abandonment marker.  
Verbal approval for plugging was obtained from Mr. Clements, NMOCD, Hobbs, 8-13-81.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <i>Francis D. Doolittle</i>	TITLE Engineering Secretary	DATE 9-9-81
APPROVED BY <i>Rozell M. Cuthbert</i>	TITLE OIL & GAS INSPECTOR	DATE AUG 28 1986
CONDITIONS OF APPROVAL, IF ANY:		