

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION  
 Orig<sup>3</sup>cc: OCC, Hobbs  
 cc: State Land Office  
 cc: Southern Region (West Texas)  
 cc: Southland Royalty Co.  
 cc: file

Form C-103  
 Supersedes Old  
 C-102 and C-103  
 Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-4025	

### SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
 USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Plugged and Abandoned		7. Unit Agreement Name
2. Name of Operator SINCLAIR OIL CORPORATION		8. Farm or Lease Name Lea 514 State Com.
3. Address of Operator P. O. Box 1920, Hobbs, New Mexico 88240		9. Well No. 1
4. Location of Well UNIT LETTER <u>K</u> , <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>32</u> TOWNSHIP <u>9S</u> RANGE <u>38E</u> NMPM.		10. Field and Pool, or Wildcat Sawyer San Andres
15. Elevation (Show whether DF, RT, GR, etc.) 3940' DF		12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
 TEMPORARILY ABANDON ☐  
 PULL OR ALTER CASING ☐  
 OTHER ☐

PLUG AND ABANDON ☐  
 CHANGE PLANS ☐  
☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐  
 COMMENCE DRILLING OPNS. ☐  
 CASING TEST AND CEMENT JOB ☐  
 OTHER ☐  
 ALTERING CASING ☐  
 PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-23-69 Plugged and Abandoned as follows:

Pumped 300 sacks regular neat cement (Type H) preceded by 30 bbls. fresh water. pumped in @ 1100 psi and pressure increased gradually to 3000 psi w/160 sacks in San Andres perms. 4916-38', left 135 sacks cement completely filling tubing F/ casing to surface. Installed regulation dry hole marker, cleaned and levelled location. Plug and Abandoned effective 1-23-69.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Superintendent DATE 1-24-69

APPROVED BY [Signature] TITLE  DATE

CONDITIONS OF APPROVAL, IF ANY: