MEXICO OIL CONSERVATION COMMASSI

SANTA FE, NEW MEXICO

Submit the notice in triplicate to the Oil Conservation Commission or its proper agent before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any medifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed,

and work should not begin until approval is obtained. See the Commission.  Indicate nature of noti		lations of
NOTICE OF INTENTION TO TEST CASING SHUT-OFF	NOTICE OF INTENTION TO SHOOT OR CHEMICALLY TREAT WELL	
NCTICE OF INTENTION TO CHANGE PLANS	NOTICE OF INTENTION TO PULL OR OTHERWISE ALTER CASING	
NCTICE OF INTENTION TO REPAIR WELL	NOTICE OF INTENTION TO PLUG WELL	X
NOTICE OF INTENTION TO DEEPEN WELL		
Midland, Texas	March 23, 1951	
OIL CONSERVATION COMMISSION, Santa Fe, New Mexico		
Gentlemen:		_
Following is a notice of intention to do certain work as desc	cribed below at the The Texas Company	's
Company or Operator State of WW MAP	Well No. in.	Swt Sat
of Sec. 20, T11-3, R38-E, I	N. M. P. M., mildcat	Field.
County.		
FULL DETAILS OF PRO	POSED PLAN OF WORK	
FOLLOW INSTRUCTIONS IN THE RULES AT TD: 10336		1
13-3/8" casing ce ented 350' with 4426 with 2700 sacis.	400 sacks. d-5/c" casing cem	ented
This well was drilled to a total de oil or gas in any commercial quanti and plug well in the following mana	ties. se therefore desire to	ering abandor
(1) Upot 35 sack cement plug 1 (2) Spot 35 sack cement plug 9 (3) Spot 35 sack cement plug 83 (4) Spot 35 sack cement plug 6 (5) Spot 35 sack cement plug 5 (6) Spot 35 sack ce ent plug 4	15351-90501 1851-90001	
MAR 29 1951	(See of	rer)
Approved, 19	The Texas Company	***************************************
except at follows:	By Janus	
	Position ist. Saut. Send communications regarding w	ell to
OIL CONSERVATION/COMMISSION,	Name The Texas Company	
By 110 GH & Gris Inspector	Address Box 1270	
Title 1	Midland, Texas	

(7) Spot 35 seek ce. nt plug 25' up in base of intermediate string.

sse of plug at 4430'.

erect a fir to be spotted in dep of surface pice. Fill cellar

erect a fir to be spotted in drill pine.

(9) Seet t plug to be spotted in drill pine.

(9) Seet t plug to be spotted in drill pine.