

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Continental Oil Company	8. Farm or Lease Name Berry 34
3. Address of Operator P. O. Box 460, Hobbs, New Mexico	9. Well No. 1
4. Location of Well UNIT LETTER <u>N</u> <u>860</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>34</u> TOWNSHIP <u>11-S</u> RANGE <u>38-E</u> NMPM.	10. Field and Pool, or Wildcat Wolfcamp
15. Elevation (Show whether DF, RT, GR, etc.) 3880 DF	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The subject well is presently producing at non-commercial rates from the Wolfcamp formation. It is proposed to plug and abandon the well using the following procedure:

1. Set CIBP @ 9425' W/2 sx Class "C" Cement.
2. Cut and pull 5 1/2" casing @ 9100' and spot 35 sx Class "C" cement from 9075-9125.
3. Cut and pull 9 5/8" casing @ 2050' and spot 40 sx Class "C" cement from 2025-2075'.
4. Spot 40 sx Class "C" Cement 0 - 50'.
5. Erect 4" X 4' high steel marker w/name and location inscribed thereon and restore the location as nearly as possible to its original condition.

Your approval of the above work is respectfully requested.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED: ROBERT CAULT III
SIGNED _____ TITLE Staff Supervisor DATE 4-28-65

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:
NMOCC-5, SLO JM Partners -4