NO. OF COPIES RECEIVED					Form C-10		
DISTRIBUTION					Supersedes C•102 and		
SANTA FE	NEW MEXICO OIL CO	ONSERVA THOUSE	OMMISSION (0.0	Effective :		
FILE		****					
U.S.G.S.		E 21	19 5	M ICE	5a. Indicate T	ype of Lease	
LAND OFFICE		LEB 74	12 45 6	כס ח	State	Fe	e. 📝
OPERATOR					5. State Oil &	Gas Lease No.	
STINIDA	Y NOTICES AND DEPORTS	ONIWELLS				THITT	7777.
(DO NOT USE THIS FORM FOR PROF	Y NOTICES AND REPORTS (POSALS TO CRILL OR TO DEEPEN OR PL ON FOR PERMIT - " (FORM C-101) FOR	UG BACK TO A DIFFER	RENT RESERVOIR	١.			
1.					7. Unit Agreer	nent Name	****
OIL X GAS WELL	OTHER-						
2. Name of Operator		······			8. Farm or Le	ase Name	
Continental Oil Co	mnany				Berry	34	
3. Address of Operator	The Carlot	· · · · ·			9. Well No.		
Box 460 Hobbs Ne	on Mexico				1		
Box 460, Hobbs, Ne	W Henrio				10. Field and	Pool, or Wildcat	
UNIT LETTER N 8		n	1980		Wolfe	amn	
UNIT LETTER,	FEET FROM THE DOUGL	LINE AND	<u> </u>	FEET FROM	ririnn	viriiii.	7777
I.I.a. or da	2)I	1 _Q	38_ਸ				/////
THE West LINE, SECTION	n TOWNSHIP	RANGE	ند- س	NМРМ.			/////
	15. Elevation (Show when	ther DF RT CR es	tc.)		12. County	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	HH
			,		Lea		IIIII
	////// 3880 DI				·		77777
Check A	Appropriate Box To Indicate	e Nature of No	tice, Repo	rt or Oth	ier Data		
NOTICE OF IN	TENTION TO:		SUBS	EQUENT	REPORT O	F:	
	,			_			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR	RK		A L	TERING CASING	
TEMPORARILY ABANDON		COMMENCE DR	ILLING OPNS.		PLU	G AND ABANDONME	ENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST	AND CEMENT JOE	• 📗		4.	
					ian & Te	ST	[_]
OTHER		$\square \mid \qquad \bigvee$	Volfcamp				
			 				
17. Describe Proposed or Completed Operurk) SEE RULE 1103.	erations (Clearly state all pertinent	details, and give p	ertinent dates,	, including	estimated date	of starting any p	roposed
Subject we zone tested in the pt 5 1/2" @ 12,135 dated 10-7-64. Pm Ran GR collar log 2 sx cmt on top. W/1 JSPF. Set RBF TD - no change PB BW in 24 hours W/8 completed 2-12-65.	5 Pay Devonian 12,000 25 BO, 1108 BW 9400-9650. Set C Perf Wolfcamp @ 9700 W/tbg. T 12050. Pay Wolfc	ure: Befo 081-12,089 in 24 hrs IBP W/wire 9482, 9485 rtd W/1850 amp 9480-9 gravity	ore work 9 W/4 JS 6. Gas eline @ 6, 9488, 0 gals a 9598. I	cover SPF. TSTM. 12,05 , 9508 acid. Pumped	TD 12,13 Latest to Work to Mork to Mor	35 csg cest done umped & 9596 workover and 12	5,
18. I hereby certify that the information	above is true and complete to the b	est of my knowledge	e and belief.				
SIGNED ROBER	RT GALLET III.						
PIGNED: KOPEK		Staff Su	aperviso	or	2.	-22-65	
SIGNEO	TITLE_				, DATE		
+							
APPROVED BY	TITLE				DATE		

NMOCC-5, SLO 2 , JM PARTNERS (4)