

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Cabot Inc.		8. Firm or Lease Name State "N" (N)
3. Address of Operator P. O. Box 1101 Pampa, Texas		9. Well No. 1
4. Location of Well UNIT LETTER 1980' FEET FROM THE N LINE AND 2330' FEET FROM THE E LINE, SECTION 35 TOWNSHIP T-10-S RANGE R-33-E NMPM.		10. Field and Pool, or Wildcat Lane
15. Elevation (Show whether DF, RT, GR, etc.) 4206		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> OTHER <input type="checkbox"/>
REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <input type="checkbox"/>	
ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

In plug and abandonment the following work was performed.

CIBP with 2 sacks cement was placed at 9500'
Cut and pulled 5728' of 4 1/2" casing
25 Sack plug at 5702'
25 Sack plug at 5360'
25 Sack plug at 4000'
Cut and pulled 1193' of 8 5/8" casing
25 sacks plug at 1180'
25 Sacks plug at 370'
10 Sack plug at 15'
Installed dry hole marker
Completed work 6-13-70

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u><i>J. L. Stibney</i></u>	TITLE <u><i>President</i></u>	DATE <u><i>6-24-70</i></u>
APPROVED BY <u><i>John W. Runyan</i></u>	TITLE <u><i>Commissioner</i></u>	DATE <u><i>AUG 11 1970</i></u>
CONDITION OF APPROVAL, IF ANY:		