

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
TRANSPORTER	OIL
	GAS
PRODUCTION OFFICE	
OPERATOR	

(Form C-102)
(Revised 1/1/62)

NEW MEXICO OIL CONSERVATION COMMISSION
Santa Fe, New Mexico

MISCELLANEOUS NOTICES

Submit this notice in **TRIPLICATE** to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO TEMPORARILY ABANDON WELL		NOTICE OF INTENTION TO DRILL DEEPER	
NOTICE OF INTENTION TO PLUG WELL	XX	NOTICE OF INTENTION TO PLUG BACK		NOTICE OF INTENTION TO SET LINER	
NOTICE OF INTENTION TO SQUEEZE		NOTICE OF INTENTION TO ACIDIZE		NOTICE OF INTENTION TO SHOOT (Nitro)	
NOTICE OF INTENTION TO GUN PERFORATE		NOTICE OF INTENTION (OTHER)		NOTICE OF INTENTION (OTHER)	

OIL CONSERVATION COMMISSION
SANTA FE, NEW MEXICO

Abilene, Texas
(Place)

1-21-64
(Date)

Gentlemen:

Coastal States Gas

Following is a Notice of Intention to do certain work as described below at the.....
Producing Company's Southern Minerals 1-15 L
Well No.in (Unit)
SW SW (Company or Operator) 15 9-S 35-E Flying M Abo
(40-acre Subdivision) 1/4 of Sec., T., R., NMPM., Pool
Lea County.

FULL DETAILS OF PROPOSED PLAN OF WORK
(FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS)

Pull out of hole with tubing. Spot 50 sk plug over perforations @ 8632 - 67'. Load casing w/ salt water. Cut 4- $\frac{1}{2}$ " casing off at free point @ 7700', and pull. Spot 35 sk plug $\frac{1}{2}$ in and $\frac{1}{2}$ out of 4- $\frac{1}{2}$ " stub. Spot 25 sk plug @ 6600', 25 sk @ 5200', 25 sk @ 4700'. Pull 7-5/8" and spot 25 sk plug over stub. Spot 25 sk in bottom of surface, 10 sk in surface, weld plate and set 10-3/4" dry hole marker. Clean up and inspect.

Approved....., 19.....
Except as follows:

Approved
OIL CONSERVATION COMMISSION

COASTAL STATES GAS PRODUCING COMPANY

By.....
Production Superintendent

Send Communications regarding well to:

Name..... Coastal States Gas Producing Co.
Address..... P. O. Box 385, Abilene, Texas