

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
<b>E-7481</b>	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
<b>Tipton &amp; Denton</b>		<b>Tapp-Stat</b>
3. Address of Operator		9. Well No.
<b>c/o Oil Reports &amp; Gas Services, Inc., Box 763, Hobbs, N M 88240</b>		<b>1</b>
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER <b>0</b> <b>660</b> FEET FROM THE <b>South</b> LINE AND <b>1980</b> FEET FROM		<b>Flying "M" Abo</b>
THE <b>East</b> LINE, SECTION <b>22</b> TOWNSHIP <b>9S</b> RANGE <b>33E</b> NMPM.		
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
<b>4349 GR</b>		<b>Lee</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> <b>Re-entry</b>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Work began 8/3/78. Installed well head and blowout preventor. Drilled surface plug, cleaned out to 2347 and hit obstruction. Ran casing swedge. Cleaned out to 3745 and hit obstruction. Ran casing swedge. Cleaned out to 5500, ran bit to 5881 and hit obstruction. Ran impression block. Ran mill and milled to 6040. Cored 1' with mill in cement, found 3 rod boxes above core. Ran bit, drilled cement to 8850 and conditioned hole. Perforated 4 1/2" casing 8762-80 with 2 holes per foot. Treated with 1,000 gallons 15% acid. Swabbed load, installed pump.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Dennis H. Wells* TITLE Agent DATE 8/30/78

APPROVED BY Orig. Signed by Jerry S. Sten TITLE  DATE AUG 31 1978

CONDITIONS OF APPROVAL, IF ANY See 1, Supv.