

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
<b>K-3706</b>	

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <b>Dry Hole</b>		7. Unit Agreement Name
2. Name of Operator <b>Ard Drilling Company</b>		8. Farm or Lease Name <b>Low State "32"</b>
3. Address of Operator <b>c/o Oil Reports &amp; Gas Services, Box 763, Hobbs, New Mexico</b>		9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>D</b> <b>660</b> FEET FROM THE <b>North</b> LINE AND <b>660</b> FEET FROM THE <b>West</b> LINE, SECTION <b>32</b> TOWNSHIP <b>9S</b> RANGE <b>35E</b> NMPM.		10. Field and Pool, or Wildcat <b>Undes. Jenkins Cisco</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4165 GR</b>		12. County <b>Lea</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input checked="" type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**Plugged and abandoned 6/24/68 as follows:**

Set cast iron bridge plug at 9750 & capped with 20 sacks cement  
Shot off 5 1/2" casing at 4783  
Spotted 40 sack plug at 4780  
Spotted 40 sack plug at 4061  
Set 10 sack plug at surface with regulation marker.  
Mud between all plugs.

**Location cleaned and levelled and ready for inspection.**

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u><i>H. L. Smith</i></u>	TITLE <u>Agent</u>	DATE <u>11/18/63</u>
APPROVED BY <u><i>John W. Remyson</i></u>	TITLE <u>Agent</u>	DATE <u>11/18/63</u>
CONDITIONS OF APPROVAL, IF ANY:		