

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>Southland Royalty Co.</b>	8. Farm or Lease Name <b>J.D. Guye</b>
3. Address of Operator <b>1405 Wilco Bldg. Midland, Texas</b>	9. Well No. <b>3</b>
4. Location of Well UNIT LETTER <b>I</b> , <b>660</b> FEET FROM THE <b>East</b> LINE AND <b>1980</b> FEET FROM THE <b>South</b> LINE, SECTION <b>12</b> TOWNSHIP <b>11s</b> RANGE <b>33 E</b> NMPM.	10. Field and Pool, or Wildcat <b>Inbe</b>
15. Elevation (Show whether DF, RT, GR, etc.)	12. County <b>LEA</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugs as follows:

100' plug over perf.  
100' " on stub of 5 1/2 csg.  
100' " @ 5357 (Glorieta)  
100' " in and out of 8 5/8 shoe  
100' " on stub of 8 5/8 csg.  
100' " in and out of 13 3/8 shoe  
10 sxs in top

100' plug 24 top wolfcamp - if not behind 5 1/2" csg.  
100' " " " " Abo - " " " " " "  
100' " " " " 5217 - " " " " 8 5/8" "  
mad between plugs  
24 hour notice to N.M.O.C.C. before setting bottom plug.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Lee Snow TITLE Agent DATE 3/12/73

APPROVED BY John W. Rangan TITLE Geologist DATE

CONDITIONS OF APPROVAL, IF ANY: