

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator BTA OIL PRODUCERS	8. Farm or Lease Name Bagley
3. Address of Operator 104 South Pecos Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER -A- 560 FEET FROM THE North LINE AND 560 FEET FROM THE East LINE, SECTION 9 TOWNSHIP 11 RANGE 33 NMPM.	10. Field and Pool, or Wildcat Bagley Permo Penn, N.
15. Elevation (Show whether DF, RT, GR, etc.) 4,273' GR	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.

P & A PROCEDURE

Spot 35 sx plug @ 8,650' EST Top @ 8,355'.
Cut & Pull 5-1/2" csg - Displace hole w/10# Brine & Gel.
Spot 50 sx plug across 5-1/2" Stub (50' in & out) - Tag.
Spot 65 sx plug @ 4,050' (8-5/8" Shoe) - Tag.
Cut & Pull 8-5/8" csg.
Spot 75 sx plug across 8-5/8" Stub (50' in & out) - Tag.
Spot 125 sx plug @ 421' (13-3/8" Shoe).
10 sx plug @ Surface

Verbal By Paul Kautz 5-3-88

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>L. D. Boyce</u>	TITLE <u>Administrative Supervisor</u>	DATE <u>5/3/88</u>
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR		
APPROVED BY _____	TITLE _____	DATE <u>MAY 5 - 1988</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

MAY 4 1988

OLD
HOBBS OFFICE