

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
E 7481	
7. Unit Agreement Name	
Flying "M" (SA) Unit Tr. 21	
8. Farm or Lease Name	
9. Well No.	
1	
10. Field and Pool, or Wildcat	
Flying "M" (SA)	
15. Elevation (Show whether DF, RT, GR, etc.)	
4305 GR	
12. County	
Lea	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER- **Water Injection Well**

2. Name of Operator  
**Coastal States Gas Producing Company**

3. Address of Operator  
**P. O. Box 235, Midland, Texas**

4. Location of Well  
UNIT LETTER **B**, **660** FEET FROM THE **north** LINE AND **1983** FEET FROM  
THE **east** LINE, SECTION **32** TOWNSHIP **9-S** RANGE **33-E** NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)  
**4305 GR**

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-28-74 - 4-1-74

1. Set Baker CIBP w/3 sx. cmt. @ 4400'. WOC 12 hrs.
2. Cut & pull 2059' of 4-1/2" casing.
3. Set 85 sx. plug @ 2054'.
4. Set 50 sx. plug @ 300'.
5. Set 10 sx. plug @ surface.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. B. Shepherd TITLE Dist. Prod. Manager DATE June 26, 1974

APPROVED BY W. J. Patterson TITLE OIL & GAS INSPECTOR DATE FEB 21 1980

CONDITIONS OF APPROVAL, IF ANY: