

Production Department Hobbs Division Western Hemisphere Petroleum Division Continental Oil Company P.O. Box 460 1001 North Turner Hobbs, New Mexico 88240 (505) 393-4141

April 6, 1976

New Mexico Oil Conservation Commission P. O. Box 1980 Hobbs, NM 88240

Attention Mr. J. T. Sexton

Gentlemen:

Enclosed is our Form C-103 dated April 6, 1976, outlining procedure to repair surface casing in State II-23 Well No. 6, located 1980' FNL and 1980' FWL of Section 23, T-10S, R-32E, State Lease No. OG-4084.

In conjunction with extensive work on this lease to bring the operations up to Continental Oil Company standards, all wells were checked for pressure on the surface pipe. A water leak was discovered at the surface on this well. It is proposed to follow procedures outlined on the enclosed Form C-103 and to patch a hole resulting from corrosion in the surface pipe immediately below the well head.

Yours very truly,

D. A. Sowers Production Superintendent

WEB:reh Enc