to Appropriate District Office	State of New M Energy, Minerals and Natural R		Form C-103 Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobba, NM 88240	OIL CONSERVATION DIVISION		WELL API NO.
DISTRICT II P.O. Drawer DD, Artesia, NM 88210 DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410		30-025-20698 5. Indicate Type of Lease	
		6. State Oil & Gas Lease No. VA-1845	
SUNDRY NOTICES AND REPORTS ON WELLS			VA-1043
(DO NOT USE THIS FORM FOR P DIFFERENT RES (FORM	ROPOSALS TO DRILL OR TO DEEPEN ERVOIR. LISE "APPLICATION FOR PE I C-101) FOR SUCH PROPOSALS.)	NOR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
1. Type of Well: OIL CAS WELL WELL	X OTHER		Comet AUC State
2. Name of Operator YATES PETROLEUM CORPO	DRATION		8. Well No. 1
3. Address of Operator		· · · · · · · · · · · · · · · · · · ·	9. Pool name or Wildcat
105 South 4th St., An 4. Well Location	rtesia, NM 88210		Eight Mile Draw Permo Penn
Unit Letter 0 : ϵ	60 Feet From The South	Line and198	0 Feet From The East Line
Section 23	Township 11S R		NMPM Lea County
	10. Elevation (Show whether	- <i>DF, RKB, RT, GR, etc.)</i> 56 'GR	
11. Checi	k Appropriate Box to Indicate		eport, or Other Data
	NTENTION TO:		SEQUENT REPORT OF
		REMEDIAL WORK	
		COMMENCE DRILLING	
		CASING TEST AND CI	
DTHER:		OTHER: Re-entry	, perforate & acidize
work) SEE RULE 1103. 2-4-2000 - Dig out of 2-5-7-2000 - Welded Scraped location and 2-8-2000 - Moved in stack. NOTE: Notif 2-9-2000 - TIH with 8:00 AM 2-8-2000. I	eellar and removed dry ho on 13-3/8" X 13-5/8" 3K l set archors. and rigged up pulling u ied Sylvia w/OCD-Hobbs 12-1/4" bit and 4-3/4" Orilled cement to 55' an	ole marker. head. Installe nit and re-entry of intent to spu drill collars an	nd spudded on surface plug at
2-10-2000 - Washed a Continued washing do Lost circulation. (2-11-2000 - Washed a at 2165'. Washed do Circulated 3 hours.	and reamed to 1360'. Do own and tagged plug at 1 Caught circulation with and reamed hole. Drille own to 2665'. Reamed ho TOOH.	ent and formatic wn 5 hours - rig 440'. Drilled c 20 bbls. Washed d bridges. Poss le. Tagged top 4 bedief. CONT	on. Washed and reamed to 1220'. g repair. Circulating. cement to 1550' and fell out. d down to 2090'. sible plug at 2160'. Fell out of 8-5/8" stub at 2985'.
2-10-2000 - Washed a Continued washing do Lost circulation. (2-11-2000 - Washed a at 2165'. Washed do Circula re d 3 hours.	and reamed to 1360'. Do own and tagged plug at 1 Caught circulation with and reamed hole. Drille own to 2665'. Reamed ho TOOH. The and complete to the best of my knowledge an MMM	ent and formatic wn 5 hours - rig 440'. Drilled c 20 bbls. Washed d bridges. Poss le. Tagged top 4 bedief. CONT	on. Washed and reamed to 1220'. g repair. Circulating. cement to 1550' and fell out. d down to 2090'. sible plug at 2160'. Fell out of 8-5/8" stub at 2985'.
2-10-2000 - Washed a Continued washing do Lost circulation. (2-11-2000 - Washed a at 2165'. Washed do Circulated 3 hours. I hereby certify that the information above in SKONATURE	and reamed to 1360'. Do own and tagged plug at 1 Caught circulation with and reamed hole. Drille own to 2665'. Reamed ho TOOH. The and complete to the best of my knowledge an fin	ent and formatic wn 5 hours - rig 440'. Drilled c 20 bbls. Washed d bridges. Poss le. Tagged top abdia. CONT me Operations T	on. Washed and reamed to 1220'. g repair. Circulating. cement to 1550' and fell out. l down to 2090'. sible plug at 2160'. Fell out of 8-5/8" stub at 2985'. TINUED ON NEXT PAGE: Cechnician DATE March 23, 2000 TELEPHONE NO. 505/748-
2-10-2000 - Washed a Continued washing do Lost circulation. (2-11-2000 - Washed a at 2165'. Washed do Circulated 3 hours. I hereby certify that the information above in SKONATURE Work the TYPE OR PRINT NAME Rusty Kle	and reamed to 1360'. Do own and tagged plug at 1 Caught circulation with and reamed hole. Drille own to 2665'. Reamed ho TOOH. The and complete to the best of my knowledge an fin	ent and formatic wn 5 hours - rig 440'. Drilled c 20 bbls. Washed d bridges. Poss le. Tagged top 4 bedief. CONT	on. Washed and reamed to 1220'. g repair. Circulating. cement to 1550' and fell out. d down to 2090'. sible plug at 2160'. Fell out of 8-5/8" stub at 2985'. TINUED ON NEXT PAGE: Cechnician DATE March 23, 2000 TELEPHONE NO. 505/748-