

COPIES RECEIVED	
TRIBUTION	
FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
----------------------------	-------------------------------------------	------------------------------

5. State Oil & Gas Lease No.

**00-124**

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>C. H. Juni</b>	8. Farm or Lease Name <b>White State</b>
3. Address of Operator <b>2104 North H Street, Midland, Texas 79701</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>P</b> , <b>965</b> FEET FROM THE <b>South</b> LINE AND <b>330</b> FEET FROM THE <b>East</b> LINE, SECTION <b>15</b> TOWNSHIP <b>10 S</b> RANGE <b>32 E</b> NMPM.	10. Field and Pool, or Wildcat <b>Mescalero San Andres</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4322 DF</b>	12. County <b>Lee</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**December 31, 1973**

1. Squeeze original perfs. 4138, 40, 43, 45, 51, 55, & 57
2. Set RTTS at 4100 ft.
3. Perf. 4077, 79, 81, 83, 85, 86, 87, 89
4. Treat above perfs with 1000 gals. acid
5. Swab test and put well on production

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED C. H. Juni TITLE Operator DATE Dec. 31, 1973

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: