

COPIES RECEIVED		
DISTRIBUTION		
FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
----------------------------	--

5. State Oil & Gas Lease No.

**09-124**

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator	8. Farm or Lease Name
3. Address of Operator	9. Well No.
4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER <b>I</b> , <b>1650</b> FEET FROM THE <b>South</b> LINE AND <b>330</b> FEET FROM THE <b>East</b> LINE, SECTION <b>15</b> TOWNSHIP <b>10 S 32</b> RANGE <b>32 E</b> NMPM.	11. <b>Mescalero</b>
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	<b>Lee</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

On or about March 26, 1974 operations were commenced to salvage this lease and well

A wire line cast iron bridge plug was set at 4000' with a 35 sk cem plug on top of it

The 5 1/2" csg. was shot at 3420' and 105 jts (3439.47') were pulled and recovered

H.O.W. CO placed 33 sk cement plug at 3445' in and out of csg. stub

HOWOCO placed a 33 sk cement plug at 1500 and at 300 across surface csg shoe

Placed a 10 sk plug at surface and set dry hole marker.

See form on #1 well concerning the notification of state for final inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED C. H. Juni TITLE Operator DATE May 8, 1975

APPROVED BY John W. Runyan TITLE Geologist DATE JUL 12 1976

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

MAY 9 1975

CIL CONSERVATION COMMISSION  
U.S. DEPT. OF AGRICULTURE