

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole	5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
2. Name of Operator Sumray DX Oil Company	5. State Oil & Gas Lease No. Unknown
3. Address of Operator P. O. Box 1416 - Roswell, New Mexico	7. Unit Agreement Name
4. Location of Well UNIT LETTER 0 , 990 FEET FROM THE South LINE AND 1650 FEET FROM THE East LINE, SECTION 18 TOWNSHIP 10-S RANGE 32-E NMPM.	8. Farm or Lease Name New Mexico "AT" State
	9. Well No. 1
	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 4385 D.F.	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Cut off 4-1/2" csg @ 3200'. Pulled 105 jts. 4-1/2" csg.
- Ran in tbgs. open ended to 4164'.
- Laid cmt plugs as follows:

15 sxs	4164' - 4000'	(Over Porosity)
25 sxs	3343' - 3164'	(In and Out of 4-1/2" stub)
25 sxs	1485' - 1410'	(Over Rustler @ 1488')
25 sxs	384' - 309'	(In and Out of 8-5/8" csg.)
10 sxs	Surface	
- Installed Dry Hole Marker. **COMPLETE 9-3-64.**
- Location has been cleaned. All pits have been filled and leveled.
- Location is ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Ralph L. Maness TITLE Acting District Engineer DATE 2-28-68

APPROVED BY John W. Runyan TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: