(Form C-104) Revised 7/1/57

REQUEST FOR (OIL) - (GAS)HALLOWABLE O. C. C.

New Well Recompletion

This form shall be submitted by the operator before an initial allowable will be assigned to any completed Oil or Gas well. Form C-104 is to be submitted in QUADRUPLICATE to the same District Office to watch file of the same allowable will be assigned effective 7:00 A.M. on date of completion or recompletion, provided this form is filed during calendar month of completion or recompletion. The completion date shall be that date in the case of an oil well when new oil is delivered into the stock tanks. Gas must be reported on 15.025 psia at 60° Fahrenheit.

				Midland, Texas					2-22-65		
					***	(Place)	**********	******************	·	(I	Date)
AR	E HERI	EBY R	EQUESTI	NG AN ALLO	WABLE FOR	R A WELL KN	IOWN	AS:			CT T
rle	8 b. G	illes	pie, Jr.	. Sta	ite 'A"	Well No	ı	in	SE		2 W
(Company or Operator) N Sec. 3			erator)	11 0	(Lease)	,,	IIndes	i anatal		···/ ~····	/
N	••••	, Sec.	<u></u>	., T 11 S	., R33 E	NMPM.	una es :	ignated	••••••	•••••	Pc
Lea				County. Da	te Spudded	0-03	Date	Drilling (completed		 FOS
P	Please inc	dicate k	ocation:	Elevation	4284 DF	2-6-65 Total	Depth_	10,204	PBT	10,	19)
				Top Oil/Gas 1	955 2	Name	of Prod	Form. Up	per Pen	nsylv	anian
D	C	В	A								
ļ]		TROBOCTIO IN	OFFO	0560			•		
	100		+	Perforations	95 52 -	·936U					
E	F	G	H	Open Hole	. •	Depth Casin	a Shoe	10,204	Depth	9.	555
							J			·	
L	K	J	I	OIL WELL TEST	, 4007 						6 1 ·
-	Α.		-	Natural Prod	. Test:	_bbls.oil,	bl	ols water in	nhr:	5,	Chok min. Siże
I			1			Treatment (afte					
M	Ņ	0	T P	iest witer At	. On Fracture	areatment (afte	r recove	th or noth	ne or oll e	equal to	Chokena
	X.	•		load oil used	i):_206bb	ls.oil, 205	bbls v	water in 24	hrs, _	min.	Size
- 1		l		GAS WELL TEST	<u> </u>						
	······································		الدوسو وسميجان		•						
					Test:	MCF/D	ay; Hour	s flowed	Chol	ce Size_	
ubing ,	,Casing a	and Ceme	nting Recor	Method of Tes	sting (pitot, b	ack pressure, et	c.):				
Size	. 1	Feet	Sax			Treatment:				£1	٠
12 2	/8 34	.5	400	1							
	/8 379		400 400	Choke Size	Method	of Testing:			i		
	/2 102	- 1	400					,			
J 1.	./ 2 102	.04	400	Acid or Fract	ure Treatment ((Give amounts of Spearhead b	materia V Wes	is used, su tern Co.	ch as acid	, water,	, oil, and
		55		sand):	8-2-4	30# Date first oil run to		7.7			
23	1/2 95	,,,	_	Casing par	Tubing 23	≀∩# Date first	new tanks	9.14.65			
2 3	/8 95	i		1 1 1 0 3 3 4 **		PP Ail run ta		Z-14-03			
2 3	95			1	Servic	oil run to	Camp	2-14-03			
2 3	95			Oil Transport	er Service	oil run to e P/ L.	Cank 5	2-14-03			
2 3	95			Gil Transport	er Servic	e P/ L.	 	2~14~03			
				Oil Transport	er Servicen none a	e P/ L.	a bana				
			77	Oil Transport	er Servicen none a	e P/ L.	a bana				7
			77	Oil Transport	er Servicen none a	e P/ L.	a bana			46	7
			<i>7</i> 7	Oil Transport	er Servicen none a	e P/ L.	a bana			10	7
marks	3:	••••••	77	Oil Transport Gas Transport	er Service none a	ce P/ L. as yet Uffli	i k	2nn	1. 1. 1.	45	7
marks I he	ereby cer	••••••	at the info	Gas Transport	ser Service none a ser	e P/ L.	the bes	en to	wledge.	16	7
marks I he	ereby cer	••••••	at the info	Oil Transport Gas Transport	ser Service none a ser	as yet	the best B. Gi	en to	wledge.	16	7
marks I he	ereby cer	rtify tha	at the info	Gas Transport	ser Service none a ser ser service above is true a service a servi	as yet	the best B. Gi	t of my kno	wledge.	15	7
marks I he	ereby cer	rtify tha	at the info	Gas Transport	ser Service none a ser ser service above is true a service a servi	as yet	the best B. Gi	of my knot liespie,	wledge. Jr.	40 1	7
marks I he	ereby cer	rtify tha	at the info	Gas Transport	ser Service none a ser ser service above is true a service a servi	as yet	the best B. Gi	t of my kno	wledge. Jr.	1	,
I he	ereby cer	rtify tha	at the info	Gas Transport	ser Service none a ser ser service above is true a service a servi	and complete to Charles	the bess B. Gi	of my knot liespie,	wledge. Jr.	13	7
I he	ereby cer	rtify tha	at the info	Gas Transport	ser Service none a ser ser service above is true a service a servi	and complete to Charles Title	the best B. Gi	t of my kno llespie, ompany or (wledge. Jr •	1	
I he	ereby cer	rtify tha	at the info	Gas Transport	ser Service none a ser ser service above is true a service a servi	and complete to Charles By: Title Send	the best B. Gi	t of my knot llespie, ompany or (Signatus erator unications	wledge. Jr. Decrator) reparting	1	
I he	ereby cer	rtify tha	at the info	Gas Transport	ser Service none a ser ser service above is true a service a servi	and complete to Charles By: Title Send Name Charle	the best B. Gi	t of my knot llespie, ompany or (Signatus erator	wledge. Jr. Decrator) reparting	1	
emarks	ereby cer	rtify tha	at the info	Gas Transport	ser Service none a ser ser service above is true a service a servi	and complete to Charles By: Title Send Name Charle	the best B. Gi	t of my knot llespie, ompany or (Signatus erator unications	wledge. Jr. Decrator) reparting	1	