

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

HOBBS OFFICE
Superior Oil
C-102 and C-103
Effective 1-1-65
MAR 2 10 40 AM '66

5a. Indicate Type Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.

E-7425

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- D & A	7. Unit Agreement Name
2. Name of Operator TEXAS PACIFIC OIL COMPANY	8. Farm or Lease Name State "AG"
3. Address of Operator P.O. Box 1069 - Hobbs, New Mexico	9. Well No. 1
4. Location of Well UNIT LETTER G , 2310 FEET FROM THE North LINE AND 1980 FEET FROM THE East LINE, SECTION 15 TOWNSHIP 10 RANGE 36 NMPM.	10. Field and Pool, or Wildcat San Andres
15. Elevation (Show whether DF, RT, GR, etc.) 4003'	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

COMMENCED OPERATIONS 2-9-66

1. Rigged up casing pulling unit and removed well head equipment.
2. Spot drilling mud from TD (4980') to 4900'.
3. Set C.I.B.P. @ 4900' w/25 sks. cement on plug.
4. Cut off casing @ 4228' and spot 25 sks. cement at cut off.
5. Pulled 5-1/2" csg. and ran tbq. Circulated fluid from hole w/drilling mud.
6. Spot 10 sks. cement plug at surface and installed dry hole marker.
7. Cleaned location and filled cellar.

COMPLETED 2-13-66

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Area Superintendent DATE 3-1-66

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: