

OIL CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
NM05812	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>Water Injection Well</u>		7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
<u>Coastal Oil &amp; Gas Corporation</u>		<u>Flying "M" (SA) Un. Tr 3</u>
3. Address of Operator		9. Well No.
<u>P. O. Box 235 Midland, Texas 79702</u>		<u>3</u>
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER <u>F</u> , 1980 FEET FROM THE <u>North</u> LINE AND <u>33E</u> FEET FROM		<u>Flying "M" San Andres</u>
THE <u>West</u> LINE, SECTION <u>17</u> TOWNSHIP <u>9S</u> RANGE <u>33E</u> NMPM.		
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
<u>4393 DF</u>		<u>Lea</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>		COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER <input type="checkbox"/>		OTHER <u>Set BP above zone and test casing</u> <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-11-83 Rigged up wireline Unit. Ran and set cast iron bridge plug at 4360-4360 1/2'.  
Dumped 5 sacks of cement (75') on top of bridge to PBTD 4285'. Pressured  
up on casing to 500 psi - held OK.

Perforations: 4418-4465'

Operations witnessed by: Mr. A. A. Plattsmier of the Oil Conservation  
Division

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. J. Wood TITLE Prod. Operations Supv. DATE 8-30-83

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT 1 SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

SEP 2 1983