NO. OF COPIES RECEIVED					
	.]				
DISTRIBUTION	NEW	MEXICO OIL C	ONSERVATION COMMISSION		Form C-104
SANTA FE		REQUEST	FOR ALLOWABLE		Supersedes Old C-104 and C-11 Effective 1-1-65
FILE			AND		Effective (-1-05
U.S.G.S.	AUTHORIZA	ATION TO TRA	A DNA JIC TROPRA	IATURAL GAS	
LAND OFFICE					
TRANSPORTER GAS					
OPERATOR					
PROBATION OFFICE					
Operator					
Sun U11 Company					
P. O. Box 2792, Ode: Reason(s) for filing (Check proper bo	s sa, Texas		Other (Please	explain)	
New Well	Change in Trans	sporter of:			
Recompletion	Oi.	Dry Go	IS S		,
Change in Ownership	Casinghead Gas	Conde	nsate //	. 4////	Land
If change of ownership give name and address of previous owner					
. DESCRIPTION OF WELL AND	LEASE	Wall No Caal No	me, Including Formation	Vinc	d of Lease
Lease Name					e, Federal or Fee State
State of New Mexico	uTu	4 Mes	scalero-San Andr	Stat	e, rederal or ree
Location Unit Letter ;	1650 Feet From The	North L	ne and 1650	_ Feet From The _	West
Line of Section 26 , To	ownship 105	Range	32E , NMPM,	Los	County
. DESIGNATION OF TRANSPOR	RTER OF OIL AND	NATURAL GA	AS		
Name of Authorized Transporter of O.	il or Condens		Address (Cive address t	o which approved co	py of this form is to be sent)
McWood, Corporation			Box 330, Ab	ilene, Texas	l .
Name of Authorized Transporter of C	asinahead Gas 🗍 or	Dry Gas		•	py of this form is to be sent)
_			· ·		
_			-		
	Unit Sec.	Twp. Age.	Is gas actually connecte	d? When	
If well produces oil or liquids, give location of tanks.				d? When	•
give location of tanks.	F 26	106 321	No		
give location of tanks. If this production is commingled w	F 26	106 321	No		
give location of tanks.	F 26	106 3215 er lease or pool,	No	number: No	g Back Same Res'v. Diff. Res'v.
give location of tanks. If this production is commingled w	rith that from any othe	106 3215 er lease or pool,	No give commingling order	number: No	g Back Same Res'v. Diff. Res'v.
give location of tanks. If this production is commingled w. COMPLETION DATA Designate Type of Complet	rith that from any other ion - (X)	105 32E er lease or pool,	No give commingling order	number: No	
give location of tanks. If this production is commingled w. COMPLETION DATA	rith that from any othe	105 32E er lease or pool,	No give commingling order	number: No	g Back Same Res'v. Diff. Res'v.
give location of tanks. If this production is commingled w. COMPLETION DATA Designate Type of Complet Date Spudded	rith that from any other ion - (X) Date Compl. Ready t	105 32E er lease or pool, Gast Well to Prod.	give commingling order New Well Workover Total Depth	number: No	T.D.
give location of tanks. If this production is commingled w. COMPLETION DATA Designate Type of Complet	rith that from any other ion - (X)	105 32E er lease or pool, Gast Well to Prod.	No give commingling order	number: No	
give location of tanks. If this production is commingled w. COMPLETION DATA Designate Type of Complet Date Spudded Pool	rith that from any other ion - (X) Date Compl. Ready t	105 32E er lease or pool, Gast Well to Prod.	give commingling order New Well Workover Total Depth	number: No Deepen Plu	T.D.
give location of tanks. If this production is commingled w. COMPLETION DATA Designate Type of Complet Date Spudded	rith that from any other ion - (X) Date Compl. Ready t	105 32E er lease or pool, Gast Well to Prod.	give commingling order New Well Workover Total Depth	number: No Deepen Plu	T.D.
give location of tanks. If this production is commingled w. COMPLETION DATA Designate Type of Complet Date Spudded Pool	rith that from any other ion — (X) Date Compl. Ready to Name of Producing F	108 32E er lease or pool, Gas Well co Prod.	No give commingling order New Well Workover Total Depth Top Oil/Gas Pay	number: No Deepen Plus P.E	T.D.
give location of tanks. If this production is commingled w. COMPLETION DATA Designate Type of Complet Date Spudded Pool	rith that from any other ion — (X) Date Compl. Ready to Name of Producing F	108 32E er lease or pool, Gas Well co Prod.	give commingling order New Well Workover Total Depth	number: No Deepen Plus P.E	T.D.
give location of tanks. If this production is commingled w. COMPLETION DATA Designate Type of Complet Date Spudded Pool	rith that from any other ion — (X) Date Compl. Ready to Name of Producing F	105 32ii er lease or pool, Gas Well o Prod.	No give commingling order New Well Workover Total Depth Top Oil/Gas Pay	number: No Deepen Plus P.E Tub	T.D.
give location of tanks. If this production is commingled w. COMPLETION DATA Designate Type of Complet Date Spudded Pool Perforations	rith that from any other ion — (X) Date Compl. Ready to Name of Producing F	105 32ii er lease or pool, Gas Well o Prod.	No give commingling order New Well Workover Tota! Depth Top Oil/Gas Pay	number: No Deepen Plus P.E Tub	oing Depth Oth Casing Shoe
give location of tanks. If this production is commingled w. COMPLETION DATA Designate Type of Complet Date Spudded Pool Perforations	rith that from any other ion — (X) Date Compl. Ready to Name of Producing F	105 32ii er lease or pool, Gas Well o Prod.	No give commingling order New Well Workover Tota! Depth Top Oil/Gas Pay	number: No Deepen Plus P.E Tub	oing Depth Oth Casing Shoe
give location of tanks. If this production is commingled w. COMPLETION DATA Designate Type of Complet Date Spudded Pool Perforations	rith that from any other ion — (X) Date Compl. Ready to Name of Producing F	105 32ii er lease or pool, Gas Well o Prod.	No give commingling order New Well Workover Tota! Depth Top Oil/Gas Pay	number: No Deepen Plus P.E Tub	oing Depth Oth Casing Shoe
give location of tanks. If this production is commingled w. COMPLETION DATA Designate Type of Complet Date Spudded Pool Perforations	rith that from any other ion — (X) Date Compl. Ready to Name of Producing F	105 32ii er lease or pool, Gas Well o Prod.	No give commingling order New Well Workover Tota! Depth Top Oil/Gas Pay	number: No Deepen Plus P.E Tub	oing Depth Oth Casing Shoe
give location of tanks. If this production is commingled w. COMPLETION DATA Designate Type of Complet Date Spudded Pool Perforations HOLE SIZE	rith that from any other ion - (X) Date Compl. Ready to Name of Producing F	105 3215 er lease or pool, Gas Well co Prod. Cormation G, CASING, AN JBING SIZE	give commingling order New Well Workover Tota! Depth Top Oil/Gas Pay Depth SE	number: No Deepen Plus P.E Tub Der	S.T.D. Sing Depth Oth Casing Shoe SACKS CEMENT
give location of tanks. If this production is commingled w. COMPLETION DATA Designate Type of Complet Date Spudded Pool Perforations HOLE SIZE	rith that from any other ion - (X) Date Compl. Ready to Name of Producing F	105 32ii er lease or pool, Gass Well co Prod. G, CASING, AN JBING SIZE	give commingling order New Well Workover Tota! Depth Top Oil/Gas Pay Depth SE	number: No Deepen Plu P.E Tub Dep	oing Depth Oth Casing Shoe
give location of tanks. If this production is commingled w. COMPLETION DATA Designate Type of Complet Date Spudded Pool Perforations HOLE SIZE	rith that from any other ion — (X) Date Compl. Ready to Name of Producing F	105 32ii er lease or pool, Gass Well co Prod. G, CASING, AN JBING SIZE	give commingling order New Well Workover Total Depth Top Oil/Gas Pay D CEMENTING RECOR DEPTH SE	number: No Deepen Plu P.E Tub Dep	SACKS CEMENT ust be equal to or exceed top allow
give location of tanks. If this production is commingled w. COMPLETION DATA Designate Type of Complet Date Spudded Pool Perforations HOLE SIZE . TEST DATA AND REQUEST I OIL WELL	rith that from any other ion - (X) Date Compl. Ready to the thickness of Producing F TUBIN CASING & TL	105 32ii er lease or pool, Gass Well co Prod. G, CASING, AN JBING SIZE	give commingling order New Well Workover Total Depth Top Oil/Gas Pay D CEMENTING RECOR DEPTH SE	number: No Deepen Plu P.E Tub Dep	SACKS CEMENT ust be equal to or exceed top allow
give location of tanks. If this production is commingled w. COMPLETION DATA Designate Type of Complet Date Spudded Pool Perforations HOLE SIZE . TEST DATA AND REQUEST I OIL WELL Date First New Oil Run To Tanks	TUBIN CASING & TU FOR ALLOWABLE Date of Test	105 32ii er lease or pool, Gass Well co Prod. G, CASING, AN JBING SIZE	give commingling order New Well Workover Total Depth Top Oil/Gas Pay DEPTH SE Offer recovery of total volumenth or be for full 24 hours Producing Method (Flow	number: No Deepen Plu P.E Tub Dep	SACKS CEMENT ust be equal to or exceed top allow
give location of tanks. If this production is commingled w. COMPLETION DATA Designate Type of Complet Date Spudded Pool Perforations HOLE SIZE . TEST DATA AND REQUEST I OIL WELL	rith that from any other ion - (X) Date Compl. Ready to the thickness of Producing F TUBIN CASING & TL	105 32ii er lease or pool, Gass Well co Prod. G, CASING, AN JBING SIZE	give commingling order New Well Workover Total Depth Top Oil/Gas Pay D CEMENTING RECOR DEPTH SE	number: No Deepen Plu P.E Tub Dep	S.T.D. Sing Depth Shing Shoe SACKS CEMENT ust be equal to or exceed top allow
give location of tanks. If this production is commingled w. COMPLETION DATA Designate Type of Complet Date Spudded Pool Perforations HOLE SIZE . TEST DATA AND REQUEST I OIL WELL Date First New Oil Run To Tanks Length of Test	TUBIN CASING & TL Date of Test Tubing Pressure	105 32ii er lease or pool, Gass Well co Prod. G, CASING, AN JBING SIZE	give commingling order New Well Workover Total Depth Top Oil/Gas Pay DEPTH SE	number: No Deepen Plu P.B Tub Dep Dep Dep Dep Cho	SACKS CEMENT SACKS CEMENT ust be equal to or exceed top allow ke Size
give location of tanks. If this production is commingled w. COMPLETION DATA Designate Type of Complet Date Spudded Pool Perforations HOLE SIZE . TEST DATA AND REQUEST I OIL WELL Date First New Oil Run To Tanks	TUBIN CASING & TU FOR ALLOWABLE Date of Test	105 32ii er lease or pool, Gass Well co Prod. G, CASING, AN JBING SIZE	give commingling order New Well Workover Total Depth Top Oil/Gas Pay DEPTH SE Offer recovery of total volumenth or be for full 24 hours Producing Method (Flow	number: No Deepen Plu P.B Tub Dep Dep Dep Dep Cho	S.T.D. Sing Depth Shing Shoe SACKS CEMENT ust be equal to or exceed top allow
give location of tanks. If this production is commingled w. COMPLETION DATA Designate Type of Complet Date Spudded Pool Perforations HOLE SIZE . TEST DATA AND REQUEST I OIL WELL Date First New Oil Run To Tanks Length of Test	TUBIN CASING & TL Date of Test Tubing Pressure	105 3215 er lease or pool, Gass Well co Prod. G, CASING, AN JBING SIZE	give commingling order New Well Workover Total Depth Top Oil/Gas Pay DEPTH SE	number: No Deepen Plu P.B Tub Dep Dep Dep Dep Cho	SACKS CEMENT SACKS CEMENT ust be equal to or exceed top allow ke Size
give location of tanks. If this production is commingled w. COMPLETION DATA Designate Type of Complet Date Spudded Pool Perforations HOLE SIZE . TEST DATA AND REQUEST I OIL WELL Date First New Oil Run To Tanks Length of Test	TUBIN CASING & TL Date of Test Tubing Pressure	105 3215 er lease or pool, Gass Well co Prod. G, CASING, AN JBING SIZE	give commingling order New Well Workover Total Depth Top Oil/Gas Pay DEPTH SE	number: No Deepen Plu P.B Tub Dep Dep Dep Dep Cho	SACKS CEMENT SACKS CEMENT ust be equal to or exceed top allow ke Size
give location of tanks. If this production is commingled w. COMPLETION DATA Designate Type of Complet Date Spudded Pool Perforations HOLE SIZE . TEST DATA AND REQUEST I OIL WELL Date First New Oil Run To Tanks Length of Test Actual Prod. During Test GAS WELL	TUBIN CASING & TU Date of Test Tubing Pressure Oil - Bbls.	105 3215 er lease or pool, Gass Well co Prod. G, CASING, AN JBING SIZE	give commingling order New Well Workover Total Depth Top Oil/Gas Pay DEPTH SE Offer recovery of total volumenth or be for full 24 hours Producing Method (Flow Casing Pressure Water-Bbls.	number: No Deepen Plu P.E Tub Dep Dep me of load oil and m) , pump, gas lift, etc Gas	SACKS CEMENT SACKS CEMENT ust be equal to or exceed top allow ske Size -MCF
give location of tanks. If this production is commingled w. COMPLETION DATA Designate Type of Complet Date Spudded Pool Perforations HOLE SIZE . TEST DATA AND REQUEST I OIL WELL Date First New Oil Run To Tanks Length of Test Actual Prod. During Test	TUBIN CASING & TL Date of Test Tubing Pressure	105 3215 er lease or pool, Gass Well co Prod. G, CASING, AN JBING SIZE	give commingling order New Well Workover Total Depth Top Oil/Gas Pay DEPTH SE	number: No Deepen Plu P.E Tub Dep Dep me of load oil and m) , pump, gas lift, etc Gas	SACKS CEMENT SACKS CEMENT ust be equal to or exceed top allow ke Size
give location of tanks. If this production is commingled w. COMPLETION DATA Designate Type of Complet Date Spudded Pool Perforations HOLE SIZE . TEST DATA AND REQUEST I OIL WELL Date First New Oil Run To Tanks Length of Test Actual Prod. During Test GAS WELL	TUBIN CASING & TU Date of Test Tubing Pressure Oil - Bbls.	105 3215 er lease or pool, Gass Well co Prod. G, CASING, AN JBING SIZE	give commingling order New Well Workover Total Depth Top Oil/Gas Pay DEPTH SE Offer recovery of total volumenth or be for full 24 hours Producing Method (Flow Casing Pressure Water-Bbls.	number: No Deepen Plu P.E Tub Dep Dep me of load oil and m) , pump, gas lift, etc Gas	SACKS CEMENT SACKS CEMENT ust be equal to or exceed top allow ske Size -MCF
give location of tanks. If this production is commingled w. COMPLETION DATA Designate Type of Complet Date Spudded Pool Perforations HOLE SIZE . TEST DATA AND REQUEST I OIL WELL Date First New Oil Run To Tanks Length of Test Actual Prod. During Test GAS WELL	TUBIN CASING & TU Date of Test Tubing Pressure Oil - Bbls.	105 3215 er lease or pool, Gass Well co Prod. G, CASING, AN JBING SIZE	give commingling order New Well Workover Total Depth Top Oil/Gas Pay DEPTH SE Offer recovery of total volumenth or be for full 24 hours Producing Method (Flow Casing Pressure Water-Bbls.	number: No Deepen Plu P.B Tub Dep Dep Dep Cho Gas	SACKS CEMENT SACKS CEMENT ust be equal to or exceed top allow ske Size -MCF

VI. CERTIFICATE OF COMPLIANCE

I hereby certify that the rules and regulations of the Oil Conservation Commission have been complied with and that the information given above is true and complete to the best of my knowledge and belief.

02	(Signature)
Area Super	<u>intendent</u>

April 22, 1965 (Date)

TITLE _ This form is to be filed in compliance with RULE 1104.

APPROVED_

If this is a request for allowable for a newly drilled or deepened well, this form must be accompanied by a tabulation of the deviation tests taken on the well in accordance with RULE 111.

OIL CONSERVATION COMMISSION

All sections of this form must be filled out completely for allowable on new and recompleted wells.

Fill out Sections I, II, III, and VI only for changes of owner, well name or number, or transporter, or other such change of condition.

Separate Forms C-104 must be filed for each pool in multiply completed wells.