

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

3c. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. 06-1826	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Injection		7. Unit Agreement Name Flying "M" (SA) Unit
2. Name of Operator Coastal Oil & Gas Corporation		8. Farm or Lease Name Flying "M" Unit Tr. 20
3. Address of Operator P. O. Box 235, Midland, Texas 79702		9. Well No. 1
4. Location of Well UNIT LETTER <u>F</u> <u>1975</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>32</u> TOWNSHIP <u>9-S</u> RANGE <u>33-E</u> N.M.P.M.		10. Field and Pool, or Wildcat Flying "M" (SA)
15. Elevation (Show whether DF, RT, GR, etc.) 4313' GR		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-26-84: Set retainer at 4303'. Squeeze below with 100 sacks Class "H" with 1500 psi. Spotted 20' of cement above retainer to 4283'. Displaced hole with 10 PPG 35 vis. mud. Spot cement 1700-1600'. SDFN.

10-27-84: Tag plug with WL, did not set up. Spot 20 sacks Class "C" with 2% CC 1719-1435'. Cut 4½" casing at 257' and POOH. Tagged plug at 1435'. Spotted 124 sacks of cement 601' to surface. Removed wellhead, weld on plate and install marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Bobby L. Smith TITLE Petroleum Engineer DATE 12-3-84  
APPROVED BY Ronald M. [Signature] OIL & GAS INSPECTOR DATE FEB 27 1985