

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

JUL 14 11 57 AM '65

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-9103
7. Unit Agreement Name
8. Farm or Lease Name Union-State 7
9. Well No. 1
10. Field and Pool, or Wildcat Wildcat
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Wm. Barnhill
3. Address of Operator P. O. Box 1354 - Roswell, New Mexico
4. Location of Well UNIT LETTER C , 660 FEET FROM THE north LINE AND 1980 FEET FROM THE west LINE SECTION 7 TOWNSHIP 11-S RANGE 38-E NMPM.
15. Elevation (Show whether DF, RT, CR, etc.)

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spudded 8-1/2" hole at 2:05 p.m., 6/18/65. Drilled to total depth of 90'. (Caliche and Sand)

7/6/65 Verbal approval obtained from Joe D. Ramey to plug and abandon well as follows:

Fill hole w/mud, set 10 sx cement in top of well w/permanent well marker set in place in accordance with Rule 202. There are no pits to be filled, location will be levelled and cleared.

No Form C-105, "Well Record", necessary as no formations were penetrated.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Wm. Barnhill TITLE Operator DATE 7-9-65

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: