

7. RIH WITH INJECTION STRING AND J ONTO ON-OFF TOOL. TEST THE TUBING AND BACKSIDE TO 500#. CIRCULATE INHIBITED FLUID. RETRIEVE THE PLUG IN THE PROFILE. RWTI.
8. ND BOP'S, RD WSU. SUBMIT A MIT TEST AND FORWARD A COPY TO THE DALLAS OFFICE.