

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

OCT 1 3 05 PM '65

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>P &amp; A</b>		7. Unit Agreement Name
2. Name of Operator <b>Shell Oil Company, Western Division</b>		8. Farm or Lease Name <b>Richardson</b>
3. Address of Operator <b>P. O. Box 1509, Midland, Texas</b>		9. Well No. <b>2</b>
4. Location of Well UNIT LETTER <b>E</b> , <b>1980</b> FEET FROM THE <b>north</b> LINE AND <b>660</b> FEET FROM THE <b>west</b> LINE, SECTION <b>30</b> TOWNSHIP <b>9-S</b> RANGE <b>33-E</b> NMPM.		10. Field and Pool, or Wildcat <b>Serr Area</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4350' df</b>		12. County <b>Lea</b>

### 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

### Spotted cement plugs as follows:

50 sx, 9100' - 8900'  
25 sx, 7300' - 7200'  
25 sx, 4800' - 4700'  
25 sx, 3700' - 3600'

Cut 8 5/8" casing at 1220' and pulled. Spotted 50 sx plug on stub.

25 sx, 400'  
10 sx, surface

Erected 4" x 4' marker

Well P & A, September 20, 1965

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Original Signed By R. J. Doubek TITLE Division Mechanical Engr. DATE Sept. 27, 1965

APPROVED BY Leslie A. Clements TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: