## **OIL CONSERVATION COMMISSION**

HOBBS, NEW MEXICO 88240

October 10, 1974

Union Texas Petroleum Corp. 1300 Wilco Bldg. Midland, Texas 79701

Gentlemen:

This office is in receipt of Form C-103 covering the plugging and abandoning of your McGuffin Well No. 1. This is being returned to you for further information.

It will be necessary that you state the footage of both the 5 1/2" and 8 5/8" casing that was pulled from the hole. Also, you state that the 3 5/8" casing parted at approximately 1400 feet, and you indicated that you spotted an 80 sack cement plug from 829 to 599 feet. Further, you have indicated on your Notice of Intent to Plug that a plug would be set in and out of the shoe of the surface casing. Form C-103 does not indicate that this plug was set. Please explain this discrepancy.

Yours very truly,

OIL CONSERVATION COMMISSION

 $\bigvee$ 

Joe D. Ramey Supervisor, District 1

JDR/mc enc1.

## **DIL CONSERVATION COMMISSION**

## HOBSS, NEW MEXICO 88240

atte des toto

Utin tests botted and "ers. 1000 Miles Pitc. Maland, Toors 7770

dentitioned:

- 1

Tuis offic () () modife of Sama 1-13 coverfuctor for plantary aif Symboly (arg of your iside))a fair for it. This it interpretated by you for famehom laforation

It will be necessary then put atta as door go of onto the off?" and 0.3/3" casing that his called from the vise, you start that the 0.5/2" cas ing partod at necestrated (400 feet, and you indicated that you sported at 60 such a control of from 200 to 300 feet. Parties, you now failested on your Cottor of Eatent to Plug that a play you'ld be set in red out of the close of the series on this discrepancy.

Yours vory bridge.

1612 CHISTORY CONTRACTOR OF ALL

Joe J. Bengy Supervisor, Cistrict I

19%/ac.