

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name J. R. Thompson
9. Well No. 1
10. Field and Pool, or Wildcat Undesignated
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Cabot Corporation
3. Address of Operator c/o Hobbs Pipe & Supply Co., Box 2010, Hobbs, N. M. 88240
4. Location of Well UNIT LETTER L 1980 FEET FROM THE South LINE AND 330' FEET FROM THE West LINE, SECTION 23 TOWNSHIP 11 RANGE 33 NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 4265' D.F.

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

1. Propose to spot a 25 sx cement plug across perforations from 9446'-55'.
2. Propose to spot a 25 sx cement plug at 5 1/2 casing stub at 6000'.
3. Propose to spot a 25 sx cement plug at 8-5/8 casing shoe at 3800'.
4. Propose to spot a 25 sx cement plug at 8-5/8 casing stub at 1000'.
5. Propose to spot a 25 sx cement plug at 13-3/8 casing shoe at 400'.
6. Propose to spot a 10 sx cement plug at surface with marker.
7. Hole will be loaded with mud laden fluids.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Joe D. Ramey TITLE Agent DATE 1/7/72

APPROVED BY Joe D. Ramey TITLE Dist. I, Supv. DATE JAN 26 1972

CONDITIONS OF APPROVAL, IF ANY: