

COPIES RECEIVED	
TRIBUTION	
FE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
E-7332

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>	
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Tipperary Oil & Gas Corporation	8. Farm or Lease Name Sinclair State
3. Address of Operator P.O. Box 3179, Midland, Texas 79702	9. Well No. 2
4. Location of Well UNIT LETTER <u>L</u> <u>660</u> FEET FROM THE <u>West</u> LINE AND <u>1980</u> FEET FROM THE <u>South</u> LINE, SECTION <u>22</u> TOWNSHIP <u>11-S</u> RANGE <u>33-E</u> NMPM.	10. Field and Pool, or Wildcat North Bagley Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4265.1	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spot 100 sx cmt @ 6764' 11-19-77. Tagged @ 5310'
Cut 4 1/2" csg @ 5126'
Spot 50 sx cmt @ 5177', tagged top @ 5036'
Spot 50 sx @ 3813'
Cut 7 5/8" csg @ 774'
Spot 50 sx cmt @ 837'.
Tagged cmt. @ 682'
Spot 50 sx cmt @ 418', tagged @ 320'
Spot 10 sx @ surface w/marker
Waiting for pit to dry for final clean up.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u>William A. Marshall</u>	TITLE <u>Petroleum Engineer</u>	DATE <u>12-2-77</u>
APPROVED BY <u>M. G. Crossland</u>	TITLE <u>OIL & GAS INSPECTOR</u>	DATE <u>JUL 27 1978</u>
CONDITIONS OF APPROVAL, IF ANY:		