

UNIT STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLIC.
(Other instructions on
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

L. C. 060909

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Brown "09"

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Sawyer San Andres Oil

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 18, T9S, R38E

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Ralph S. Cooley

3. ADDRESS OF OPERATOR

P. O. Box 254, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

**1980' from West line and 660' from South line of Section
18, Township 9-South, Range 38-East**

14. PERMIT NO.

15. ELEVATIONS (Show whether DE, RT, GR, etc.)

3968 Ground

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Plugging procedure approved November 1, 1967.

- 1. December 7, 1967 - Placed cement plug 4775' to total depth 5019' inside 4-1/2 inch casing.**
 - 2. Loaded hole with 10 pound mud and pumped against plug. Plug holding. W.O.C.**
 - 3. December 8, 1967 - Shot 4-1/2 inch casing at 1540'. Pipe free. Picked up one joint. Placed one hundred feet cement plug 1600' to 1500' across 4-1/2 inch casing stub. W.O.C. then pumped against plug. Plug holding.**
 - 4. Pulled 4-1/2 inch casing to 300 feet. Spotted cement plug 350 feet to 450 feet across shoe of 8-5/8 inch surface casing. W.O.C.**
 - 5. December 9, 1967 - Tested plug at base of 8-5/8 inch casing. Holding o.k. Pulled remaining 4-1/2 inch casing.**
 - 6. Placed 35 feet cement plug in top of 8-5/8 inch surface casing.**
 - 7. Erected marker 4-1/2 feet above ground level.**
 - 8. Cleaned up location.**
- Work has been completed. Ready for inspection.**

18. I hereby certify that the foregoing is true and correct

SIGNED

Ralph S. Cooley

TITLE

Operator

DATE **January 9, 1968**

(This space for Federal or State office use)

APPROVED

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

DEC 11 1968

*See Instructions on Reverse Side

J. L. GORDON
ACTING DISTRICT ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.