

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE
(Other instructions on
reverse side)

NEW MEXICO

COPY TO O. & G.

Form approved.
Budget Bureau No. 42-R1424.
LEASE DESIGNATION AND SERIAL NO.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Tipperary Oil & Gas Corporation		8. FARM OR LEASE NAME Andover Federal	
3. ADDRESS OF OPERATOR P.O. Box 3179, Midland, Texas 79702		9. WELL NO. 1	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 810' FSL & 660' FEL of Sec. 17, T-11-S, R-33-E		10. FIELD AND POOL, OR WILDCAT North Bagley Penn	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4280' DF	
		11. SEC. T., R., M., OR BLK. AND SURVEY OR AREA Sec. 17, T-11-S, R-33-E	
		12. COUNTY OR PARISH Lea	
		13. STATE N.M.	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
(Other) Perforate New Zones	<input checked="" type="checkbox"/>		

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Pull rods & tbgs. & rig up BOP.

Perforate: 9915, 9634, 9603, 9311, 9203, 9074, 8976, 8784, & 8546

Acidize with 500 gals 15% NE acid each.

Work should commence by the first week in August, 1977.

18. I hereby certify that the foregoing is true and correct

SIGNED William F. Mall TITLE Petroleum Engineer

DATE July 21, 1977

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____
CONDITIONS OF APPROVAL, IF ANY:

APPROVED
DATE JUL 22 1977
Bernard Moroz
BERNARD MOROZ
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

ALL INFORMATION CONTAINED
HEREIN IS UNCLASSIFIED

DATE 10/17/07
BY 60322
OIL COMPANY
HOBBS, N. M.