Fee X

	, #	Fage 1 of 2	
OF COPIES MECEIVED	· · · · · · · · · · · · · · · · · · ·	Form C-103 Supersedes Old C-102 and C-103	
DISTRIBUTION	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65	
ANTAFE	NEW MEXICO OIL CONSERVATION COMMISSION		
ILE		Sa. Indicate Type of Lease	
s.G. <b>s</b> .		State F	
LAND OFFICE		5. State Ch & Gas Lease No.	
PERATOR			
SUNDE	7, Unit Agreement Name		
OIL X GAS MELL	OTHER•	8, Form or Lease Name	
. Name of Cyeratur		Pruitt	
The Maurice L. Brown Company		9. Weil No.	
Attress of Cherater	lace Bldg /Wichita, Kansas 67202	1	

SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM ) IN ENCROSALS TO DETILL ON TO DEEDLE OR FILLS BACK TO A DIFFERENT RESERVOIR.  (DO NOT USE THIS FORM ) IN ENCROSALS TO DETILL ON TO DEEDLE OR FILLS BACK TO A DIFFERENT RESERVOIR.	
IDO NOT USE THIS FOR PERMIT AT FORM C-101 FOR SICH PROPUSACES	7. Unit Agreement Name
OIL GAS OTHER.	8, Form or Lease Name
Fine of Eperatur	Pruitt
he Maurice L. Brown Company	9. Weil No.
Clear of Control	1
uite 200/Sutton Place Bldg./Wichita, Kansas 67202	10. Field and Pool, or Wildcat
continue ( Wall	Vada Penn
UNIT LETTER B . 660 FEET FROM THE NORTH LINE AND 1980 FEET FROM	
THE East LINE, SECTION 20 TOWNSHIP 9-S RANGE 34-E NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	Lea
4284 GR	nor Data
Check Appropriate Box To Indicate Nature of Notice, Report or Other	REPORT OF:
NOTICE OF INTENTION TO:	REPORT OF
PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS.	ALTERING CASING PLUG AND ABANDONMENT

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-27-79

FULL OR ALTER CASING

Move in and rig up PBCP Services, Inc.

10-29-79

POH with 222 joints 2 3/8" EUE tubing.

Completed POH with tubing. Ran gauge ring on SL to 9760'. Ran CIBP to 9760'. 10-31-79

Spotted 3 sacks cement on BP to form 35' cement plug.

CHANGE PLANS

Completed going in hole with tubing. Loaded hole with mud laden brine. POH with tubing.

Welded onto  $4\frac{1}{2}$ " casing. Shot casing in collar at 4005' depth by WL measure. Laid down 35 joints  $4\frac{1}{7}$ " casing.

. ONDITIONS OF APPROVAL, IF ANY:

Completed laying down 45" casing. Had 126 joints (4033.05') 45" N & J, 11.6# LT & C 8 RT casing. Will with tubing. Spotted 50 sacks cement at 4055'. Pulled tubing to 2250'.

. I hereby certify that the information above is true and complet	e to the best of my knowledge and belief.	
1 hereby certify that the information agost 15 cm.	District Engineer	11-9-79
INED WIVE . DU CONTRA		
PROVED BY Lili Flatformen	HILL CALL GO CALLED INSPECTOES	LATE

. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	 ļ
J.S.G.\$.	 
LAND OFFICE	 -
PERATOR	 

Form 2-103

. OF COPIES RECEIVED		Supersedes Old
DISTRIBUTION	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103 Fitective 1-1-65
ANTAFE	NEW MEXICO OIL CONSERVATION COMMISSION	
ILE	<u></u>	State Fee X
s.g.\$.		
AND OFFICE	_	5. State Ni. & Gas Lease No.
PERATOR		mmmmm-
CHND	RY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THE FORM F H F	RY NOTICES AND REPORTS FLUG BACK TO A DIFFERENT RESERVOIR.	7. Unit Agreement Name
OIL X GAS WELL	OTHER.	8. Farm of Lease Name
Come of Cyerotor The Maurice L. Bro	own Company	Pruitt
Address of Operator Suite 200/Sutton	Place Bldg./Wichita, Kansas 67202	1 10. Field and Fool, or Wildeat
Location of Well	660 PEET FROM THE North LINE AND 1980! PEET	W-d- Down
UNIT LETTER B		Marie
East_LINE, SEC	TION 20 TOWNSHIP 9-S RANGE 34-E	
	15. 1 levation (Show whether DF, RT, GR, etc.) 4284 GR	Lea
	4204 - GIT	Other Data
Chec	k Appropriate Box To Indicate Nature of Notice, Report of Subsequential To:	JENT REPORT OF:
,, NOTICE OF		ALTERING CASING
ERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	PLUG AND ABANDONMENT
EMPORARILY ABANDON	COMMENCE DRILLING OPNS.  CASING TEST AND CEMENT JOB	1
ULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMEN 340	
OTHER	dates, inc	luding estimated date of starting any proposed
7. Describe Proposed or Complete	d Operations (Clearly state all pertinent details, and give pertinent dates, inc	
work) SEE HOLE !!		
11-05-79	plug at 3900' (155' of fill). Spotted	d 35 sacks at 2250'.
Tagged top cement	Stronging.	
Welded onto 8 5/8	, casing.	(4405 201) 9 5/81
11-00-/9	107' by WL measurement. Laid down 35 j	oints $(1107.32.7 \circ 570)$
snot o 9/0 at 1	70 sacks cement through tubing at 1160	' depth.
11_07_79	(4/01 0:17)	Snotted 70 sacks
Tagged top of cer	ment with tubing at 1000'. (160' fill)	. Spotted 70 Sacks
cement at 421'.	Tagged top of cement at 310'. Laid do	marker. Rigged down
Spotted 10 sacks	cement at surface and orders and	marker
PBCP Services, I	nc.	
I thereby conside that the inform	nation above is true and complete to the best of my knowledge and belief.	
1 unitary carries and and		11 0 70
11 mm Mr	OFS DECK District Engineer	2 (A11) (11) = Y= <u>AY</u>
I.NIO WILLIAM		
117	theorem In San & CAS INSPEC	THE REAL PROPERTY OF THE PROPE
11.11.717	Tamus mu de de la	
A. PHOVER BY		