

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.	30-025-22016
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	K-2604
7. Lease Name or Unit Agreement Name	
Bagley-State	
8. Well No.	3
9. Pool name or Wildcat	Bagley Permo Penn, North
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
4283' GL	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	Sabre Operating Inc.
3. Address of Operator	P.O. Box 4848 Wichita Falls, Tx 76308-0848
4. Well Location	Unit Letter C : 1980 Feet From The West Line and 660 Feet From The North Line
Section 16	Township 11S Range 33E NMPM Lea County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NOTIFY NEW MEXICO CONSERVATION COMMISSION 24HRS. BEFORE OPERATIONS BEGIN. (505) 393-6161

(1) Well TA 4/26/91 CIBP set @ 8600' w/2sx. cmt. (C-103 Attached)
 (2) Circ. hole w/mud laden fluid.
 (3) 25sx. 6200' in 5½" csg.
 (4) 50sx. 5½" stub plug apprx. 5000'
 (5) 50sx. 8-5/8" shoe plug 3850'-3750' (WOC-TAG)
 (6) 50sx. 8-5/8" stub plug apprx. 700'
 (7) 80sx. 8-5/8" shoe plug 425'-325' (WOC-TAG)
 (8) 20sx. 30'-0'
 (9) Install dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Erelan Fields TITLE Agent DATE 2/13/96

TYPE OR PRINT NAME Erelan Fields (915)366-1852 TELEPHONE NO. _____

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE FEB 20 1996

CONDITIONS OF APPROVAL, IF ANY:

[Handwritten initials]

