DISTRIBUTION SANTA FE		
SANTAFE		Supersedes Old C-102 and C-103
	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE		
U.S.G.S.		5a. Indicate Type of Lease
		State X Fee
LAND OFFICE		
OPERATOR		5, State Oil & Gas Lease No. 9943
SHINE	DRY MOTICES AND DEPORTS ON WELLS	
OO NOT USE THIS FORM FOR I USE "APPLIC	DRY NOTICES AND REPORTS ON WELLS PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR CATION FOR PERMIT - FORM C-101) FOR SUCH PROPOSALS.)	
		7. Unit Agreement Name
OIL GAS WELL WELL	OTHER-	
2. Name of Operator		8. Farm or Lease Name
Cities Service Oi	il Company	State AD
Address of Operator		9. Well No.
	obbs, New Mexico 88240	
Location of Well	000	10. Field and Pool, or Wildcat
UNIT LETTER 0	800 FEET FROM THE South LINE AND 1980	Mescalero Permo Penn.
	••	
THE East Line, sec	CTION 22 TOWNSHIP 105 RANGE 32E	NMPM.
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	4343 D.F.	Lea (\\\\\\\\
. Check	k Appropriate Box To Indicate Nature of Notice, Repor	et on Othor Doto
NOTICE OF	INTENTION TO:	EQUENT REPORT OF:
F*		
ERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
POCHABLY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
OLL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	
OTHER ACIDIZE MESCA	alero Permo Penn X	
OTHER		
	As solding Abs Massaline Basis Basis	
l. Pull r	to acidize the Mescalero Permo Penn formatireds and tubing.	on in the following manner:
l. Pull r 2. nstal	rods and tubing.	on in the following manner:
 Pull r Instal Set pa Acidiz 	rods and tubing.	
 Pull r Instal Set pa Acidiz 	rods and tubing. II BOP. acker at approximately 92934. Ze Mescalero Permo Penn with 3000 gallons of	
 Pull r Instal Set pa Acidiz 	rods and tubing. II BOP. acker at approximately 92934. Ze Mescalero Permo Penn with 3000 gallons of	
 Pull r Instal Set pa Acidiz 	rods and tubing. II BOP. acker at approximately 92934. Ze Mescalero Permo Penn with 3000 gallons of	
l. Pull r 2. Instal 3. Set pa 4. Acidiz Hydroc	rods and tubing. II BOP. acker at approximately 92934. Ze Mescalero Permo Penn with 3000 gallons of	
1. Pull r 2. Instal 3. Set pa 4. Acidiz Hydroc	rods and tubing. II BOP. acker at approximately 9293'. Ze Mescalero Permo Penn with 3000 gallons of chloric acid.	28%
1. Pull r 2. Instal 3. Set pa 4. Acidiz Hydroc	rods and tubing. II BOP. acker at approximately 9293'. Ze Mescalero Permo Penn with 3000 gailons of chloric acid. ion above is true and complete to the best of my knowledge and belief.	28% DATE 9-25-68
 Pull r Instal Set pa Acidiz Hydroc 	rods and tubing. II BOP. acker at approximately 9293'. Ze Mescalero Permo Penn with 3000 gallons of chloric acid.	28% DATE 9-25-68
1. Pull r 2. Instal 3. Set pa 4. Acidiz Hydroc	rods and tubing. II BOP. acker at approximately 9293'. Ze Mescalero Permo Penn with 3000 gallons of chloric acid. ion above is true and complete to the best of my knowledge and belief. TITLE District Clerk	28% DATE 9-25-68
1. Pull r 2. Instal 3. Set pa 4. Acidiz Hydroc	rods and tubing. Il BOP. acker at approximately 9293'. Ze Mescalero Permo Penn with 3000 gailons of chloric acid. ion above is true and complete to the best of my knowledge and belief. TITLE District Clerk	28% DATE 9-25-68