

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

3a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>	
3. State Oil & Gas Lease No. V-16	
7. Unit Agreement Name	
8. Farm or Lease Name Susco Bough "C" Unit	
9. Well No. 1	
10. Field and Pool, or Wildcat Inbe Permo Penn	
15. Elevation (Show whether DF, RT, GR, etc.) 4196.5 GR	
12. County Lea	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1.  OIL WELL  GAS WELL  OTHER- SPB

2. Name of Operator  
Southern Union Exploration Company

3. Address of Operator  
1217 Main Street, Suite 400, Dallas, Texas 75202

4. Location of Well  
UNIT LETTER J 1980 FEET FROM THE East LINE AND 1980 FEET FROM  
THE South LINE, SECTION 35 TOWNSHIP 10S RANGE 33E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)  
4196.5 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIATION WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

- Spotted a 30 sk cement plug at 9684'. WOC. RIH & did not find plug.
- Spotted a 30 sk cement plug at 9694'. WOC. RIH & tagged the TOC @ 9012'.
- Circulated the well with 10 ppg brine containing 45 sks of mud.
- RIH & cut the 5 1/2" casing at 4395'. POH & laid down 4395' of 5 1/2" casing.
- Spotted a 50 sk cement plug at 4445'. WOC. RIH & tagged the TOC @ 4345'.
- Spotted a 60 sk cement plug at 4040'. WOC. RIH & tagged the TOC @ 3937'.
- Spotted a 65 sk cement plug at 450'.
- Cut off the wellhead and spotted a 5 sk cement surface plug.
- Welded on plate and installed dry hole marker.
- Cleaned off and leveled location.

The work was performed from 1/3/86 - 1/22/86.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED David W. Stevens TITLE Drilling & Production Engineer DATE 1/29/86

APPROVED BY Lyle F. Turnacliff TITLE OIL & GAS INSPECTOR DATE APR 1 - 1986

CONDITIONS OF APPROVAL, IF ANY: