

CONSERVATION DIVISION
P. O. BOX 2083
SANTA FE, NEW MEXICO 87501

Form C-101
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5. Indicate Type of Lease
State ☒ Federal ☐
6. State Oil & Gas Lease No.
K 3724

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER	7. Unit Agreement Name None
2. Name of Operator SAGE ENERGY COMPANY	8. Farm or Lease Name Cabot State
3. Address of Operator P.O. Drawer 3068, Midland, Texas 79702	9. Well No. 3
4. Location of Well UNIT LETTER <u>A</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>32</u> TOWNSHIP <u>T-8-S</u> RANGE <u>R-36-E</u> N.M.P.M.	10. Field and Pool, or Wildcat Vada Penn
11. Elevation (Show whether DF, RT, GR, etc.) 4117' RKB	12. County Roosevelt

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☒
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) 4/30/86 - 5/1/86 - Spotted 150 sacks of "C" Cement @ 9650'. Tagged Plug @ 9250'.
- 2) 5/5/86 - Set CIBP @ 7100'.
- 3) 5/5/86 - Attempted to cut and pull pipe. Cut @ 4350'.
- 4) 5/6/86 - Spotted 50 sacks of "C" Cement @ 5000'.
- 5) 5/6/86 - Squeezed 70 sacks of "C" Cement @ 4350'.
- 6) 5/6/86 - Attempt to pull 5½ from 2500' and 1400'. Pipe stuck.
- 7) 5/6/86 - Pumped 35 sacks of "C" Cement @ 2500'.
- 8) 5/6/86 - Cut and pulled 1700' of 5½" pipe.
- 9) 5/6/86 - Pumped 50 sacks of "C" Cement @ 1300'.
- 10) 5/7/86 - Tag plug @ 1071'.
- 11) 5/7/86 - Spot 60 sacks @ 400' and 10 sacks @ surface.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Fred M. Newman TITLE Cementer DATE May 7, 1986

APPROVED BY Ronald M. Callahan TITLE OIL & GAS INSPECTOR DATE May 7, 1986

CONDITIONS OF APPROVAL, IF ANY: