

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPL  
(Other instructions  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.  
LC-071392

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

HOBBS OFFICE O. C. C.  
APR 6 7 35 AM '64

1. OIL WELL  GAS WELL  OTHER Dry Well (Never produced oil)

2. NAME OF OPERATOR  
Great Western Drilling Company

3. ADDRESS OF OPERATOR  
P. O. Box 1659, Midland, Texas

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface SE/4 of NE/4 of Sec. 10, T-13-S, R-31-E  
330' from East line and 2260' from North  
line of Section.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)  
4424 Gr.

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME  
Pebble Queen Unit

8. FARM OR LEASE NAME

9. WELL NO.  
10-8

10. FIELD AND POOL, OR WILDCAT  
Caprock Queen

11. SEC., T., B., M., OR BLK. AND SURVEY OR AREA  
10-13-S, 31-E

12. COUNTY OR PARISH  
Chaves

13. STATE  
New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Great Western Drilling Company, by agreement with Pebble Queen Operators, plan to place 25 sacks of cement at the top of the Queen sand or at 3015'. The oil string will be pulled where free, estimated at (1100-1500) and a 25 sack plug placed in the stub. A 15 sack plug will be placed at the shoe of the surface pipe (about 300') with 10 sacks at the surface. A cleanup will be made and a proper marker placed.

APPROVED  
APR 3 1964  
*B. J. [Signature]*  
B. J. [Signature]

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature]

TITLE Adm. Coordinator

DATE 3/31/64

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_

TITLE \_\_\_\_\_

DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side