

|                        |  |
|------------------------|--|
| NO. OF COPIES RECEIVED |  |
| DISTRIBUTION           |  |
| SANTA FE               |  |
| FILE                   |  |
| U.S.G.S.               |  |
| LAND OFFICE            |  |
| OPERATOR               |  |

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease

State ☒ Fee ☐

5. State Oil & Gas Lease No.

**K-3259**

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

|  |   |
|--|---|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>   | 7. Unit Agreement Name                                  |
| 2. Name of Operator<br><b>Sun Oil Company</b>  | 8. Farm or Lease Name<br><b>New Mexico "J" State</b>    |
| 3. Address of Operator<br><b>P. O. Box 2792, Odessa, Texas 79760</b>   | 9. Well No.<br><b>1</b>                                 |
| 4. Location of Well<br>UNIT LETTER <b>K</b> , <b>1980</b> FEET FROM THE <b>West</b> LINE AND <b>1980</b> FEET FROM<br>THE <b>South</b> LINE, SECTION <b>36</b> TOWNSHIP <b>7 S</b> RANGE <b>30 E</b> NMPM. | 10. Field and Pool, or Wildcat<br><b>Milnesand Cate</b> |
| 15. Elevation (Show whether DF, RT, GR, etc.)<br><b>4201' Gr.</b>  | 12. County<br><b>Chaves</b>                             |

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐  
CHANGE PLANS ☐

OTHER **Acidize btm 7 perfs in Gato & P-3 Zones (3591-3689)** ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOBS ☐  
OTHER ☐

ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Pull rods and pump, unseat pkr and pull tubing and pkr. Run tbg w/HD & hook-wall pkr. Acidize btm seven perfs. w/5000 gals. 28% NE Hel using ball sealers. Flush with 6500 gals treated fresh water. Pull packer, helddown and tubing. Re-run tubing, rods and pump.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED John M. Sweeney TITLE Ass't District Superintendent DATE 12-6-68

APPROVED BY [Signature] TITLE SUPERVISOR DATE DEC 8 1968

CONDITIONS OF APPROVAL, IF ANY: