

UNITED STATES N. M. DEPT. OF THE INTERIOR  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY HOBBS, NEW MEXICO 88240

Form approved.  
Budget Bureau No. 42-R1424.  
5. LEASE DESIGNATION AND SERIAL NO.

NM 37852

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> DRY	7. UNIT AGREEMENT NAME N/A
2. NAME OF OPERATOR JACK J. GRINBERG	8. FARM OR LEASE NAME FEDERAL 34
3. ADDRESS OF OPERATOR 5000 S. QUEBEC ST., SUITE 500 DENVER, COLORADO 80237	9. WELL NO. <del>134</del> /
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 990' FSL's 990' FWL Unit m	10. FIELD AND POOL, OR WILDCAT OASIS ABO
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4087' K.B.
	12. COUNTY OR PARISH CHAVES
	13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) _____	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

THE SUBJECT WELL WAS PLUGGED AND ABANDONED IN THE FOLLOWING MANNER:

PLUG #	INTERVAL	SACKS OF CEMENT
1	6,590 - 6,430	60 SXS CLASS "H"
2	4,130 - 3,990	65 SXS CLASS "H"
3	1,660 - 1,540	50 SXS CLASS "H" w/ 2% CaCl PLUG TAGGED
4	493 - 393	30 SXS CLASS "H"
5	SURFACE	15 SXS CLASS "H"

DRY HOLE MARKER INSTALLED

RIG RELEASED 6:00 AM 1-5-90

VERBAL APPROVAL GIVEN BY PETE CHESTER 1-3-90

18. I hereby certify that the foregoing is true and correct

SIGNED Pete W. Chester TITLE Drilling/Completion Engineer DATE 1-8-90

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:  
Approved as to plugging of the well bore.  
Liability under bond is retained until  
surface restoration is completed.

APPROVED  
PETER W. CHESTER  
JAN 18 1990  
\*See Instructions on Reverse Side  
BUREAU OF LAND MANAGEMENT  
ROSWELL RESOURCE AREA

