

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-005-21111

3. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Well Agricultural Name

D.J. Fee

1. Type of Well:
Oil Well Gas Well Other

8. Well No.
1-Y

2. Name of Operator
Manzano Oil Corporation 505/623-1996

9. Field name or Wellhead
Cato San Andres

3. Address of Operator
P.O. Box 2107/Roswell, NM 88202-2107

4. Well Location
Unit Letter G : 1659 Feet From The North Line and 1745 Feet From The East Line
Section 35 Township 7 South Range 30 East NMPM Chaves County

10. Elevation (Show whether DF, RKB, RT, CR, etc.)
4164' GL/4175' KB

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-24-92 TD 3700'. Ran 104 jts of 5-1/2" 17# 15.50# J55 LT&C 8 rnd w/auto flr, flt shoe, flt clr, 10 centrl & DV tool. Set @ 3700'. Cmtd in 2 stages. 1st stage cmtd w/350 sks C1 H w/8#/sk CSE. 2nd stage cmtd w/400 sks C1 C Neat.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Allison Rolfe TITLE Production Analyst DATE 4/27/92
TYPE OR PRINT NAME Allison Rolfe TELEPHONE NO. 623-1996

(This space for State Use)
ORIGINAL SIGNED BY RAY SMITH
FIELD REP. II

APR 29 '92

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
12 28 1992
HOO HOBBS OFFICE